Kia

SPORTAGE 1.6 T-GDI MHEV 150 CV PRESTIGE

VIN: U5YPV81BANL040885

Description

Registration number	**Registration date**	**Odometer**
GL-101-TS	24/01/2023	80014 km
Color	**Year**	**Upholstery**
Black	-	-
Number of doors	**Number of seats**	**Generation**
-	-	-
Body Type	**Vehicle Type**	**Engine type**
Sport Utility Vehicule	Passenger car	Combustion
Fuel Type	**Max power**	
Petrol	150 HP	

Vehicle Equipments

Rear-view camera	Climate control	Alloy wheel rims
Xenon headlights	Rear sensors	Front sensors
Cruise control	SATNAV	

Statement details

Inspection loc	Statement date	Inspection approval date
NICE (CAGNES) - GCA (TEA)	03/09/2025	04/09/2025

Control

Engine start issue	**Is not roadworthy**
No	No

Defects & corrections

#	Element	Defect	Correction
1	Compressor tyre repair kit / -	Missing	Replace

2	Rear parcel shelf / -	Missing	Replace

3	Refill emergency kit / -	Missing	Replace

4	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17 "	Scratched	Repair

5	Wing moulding / Front Right	Scratched	Painting

6	Bumper moulding / Front Right	Scratched	Painting

7	Door / Front Left	Dent	Smart repair

8	Door / Back Left	Dent	Repair

9	Bumper / Back Left	Scratched	Acceptable

10	Spoiler / Back	Scratched	Painting

11	Bumper / Back Right	Scratched	Painting

12	Bumper moulding / Back Right	Scratched	Painting

13	Bumper / Back	Scratched	Painting

14	Wing / Back Right	Dent	Repair

15	Door / Back Right		Dent	Repair

16	Door / Front Right		Dent	Repair

Loose Items

- [ ] Slow charging cable
- [x] Warranty booklet
- [x] Remote key
- [ ] Cargo net
- [ ] Rear parcel shelf

- [ ] Quick charging cable
- [ ] Memory card
- [ ] Compressor tyre repair kit
- [ ] Separation net
- [ ] Refill tyre repair kit

- [ ] Load cover
- [ ] Locking wheel nut
- [ ] Jack
- [x] User manual
- [ ] Spare wheel tyre

Main set of tyres

Front Left	GT RADIAL	215 / 65 / 17 / All	6.3 mm
Front Right	GT RADIAL	215 / 65 / 17 / All	6.2 mm
Back Left	MICHELIN	215 / 65 / 17 / All	5.2 mm
Back Right	MICHELIN	215 / 65 / 17 / All	4.5 mm

Pictures

Front left

Rear

Boot opened

Rear right

Dashboard from rear seat

Front passenger compartment

Odometer

Navigation

Spare Tyre

Vin

Compressor tyre repair kit / - / Missing


Rear parcel shelf / - / Missing

Refill emergency kit / - / Missing

Rim / Front Right / Scratched

Rim / Front Right / Scratched

Wing moulding / Front Right / Scratched

Wing moulding / Front Right / Scratched

Bumper moulding / Front Right / Scratched

Bumper moulding / Front Right / Scratched

Door / Front Left / Dent

Door / Front Left / Dent

Door / Back Left / Dent

Door / Back Left / Dent


Bumper / Back Left / Scratched

Bumper / Back Left / Scratched

Spoiler / Back / Scratched

Spoiler / Back / Scratched

Bumper / Back Right / Scratched

Bumper / Back Right / Scratched

Bumper moulding / Back Right / Scratched

Bumper moulding / Back Right / Scratched

Bumper / Back / Scratched

Bumper / Back / Scratched

Wing / Back Right / Dent

Wing / Back Right / Dent

Door / Back Right / Dent

Door / Back Right / Dent

Door / Front Right / Dent

Door / Front Right / Dent