DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Vehicle details

VIN	VF7PSCFB7 LR552936	Brand	Citroï¿½n	Maintenance date	-
Licence Plate	J4-03-LF	Model	C1 VTi 72 S;S ActieAuto 5d Feel APL	Maintenance mileage	-
Registration date	07/09/2020	Year	2020	Exterior Color	White Solid
Odometer	69 694 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	08/09/2025	Inspection loc.	Ayvens Veghel



Generic equipment

Manual air-conditioning	✔
Central locking	✔
Electric windows	✔
Audio System	✔

Removable element

Spare wheel kit	✔
Rear parcel shelf	✔

Technical Document

User manual	✔
Warranty booklet	✔
Key	✔
Remote key	✔

Tyres

Continental 165/60/15 Summer 3.0 mm

Continental 165/60/15 Summer 3.0 mm



Continental 165/60/15 Summer 5.0 mm

Continental 165/60/15 Summer 5.0 mm

Exterior

2



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4

Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning