DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Vehicle details

VIN	VXKUPHMHD L4406442	Brand	OPEL	Maintenance date	-
Licence Plate	J3-03-ZJ	Model	CORSA 1.2 EDITION 55KW ACTI Corsa 2020 APL 5d	Maintenance mileage	-
Registration date	12/11/2020	Year	2020	Exterior Color	Black Metallic
Odometer	50 027 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	28/10/2025	Inspection loc.	Dekra Ayvens



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Michelin 185/65/15 Summer 5.5 mm

Michelin 185/65/15 Summer 5.0 mm



Continental 185/65/15 Summer 5.0 mm

Continental 185/65/15 Summer 5.0 mm

Exterior

2

Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Number > 2
Repair mode	Repair

3

Part	Alloy wheel 15"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

4

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6

Part	Roof post A/B/C
Position	Right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

7



Part	Roof
Position	-
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

Interior damage

1

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning