OPEL Corsa
Corsa 1.2

VIN NO W0L0XEP68G4131657

Registration Number 68G4131657

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-08-01	2	2	160863 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
2019-08-09	41840	2016-03-02	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250822123359
Inspection Date / Place	2025-08-22 / Dürkop Berlin-Prenzlauer Berg	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1229
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	128
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Trip Computer	Airbag Status	Bluetooth telephone interface	Enhanced speaker system
Remote adjusting wing mirrors	CD Player	Leather steering wheel	USB Socket
Anti-lock braking	Cruise control	Front fog lamps	Stability control
Central locking	Radio		

Equipment Details

Air Conditioning	Yes	Seat Heating	No

Wheels & Tyres

Right Front Tyre Depth	6	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage





	Component	Damage	Comments
1	Bumper / Back	Paint / Scratch / Scuff	
2	Side Panel / Back Right	Paint / Scratch / Scuff	
3	Door / Back Right	Paint / Scratch / Scuff	
4	Fender / Front Right	Paint / Scratch / Scuff	
5	Tailgate	Bodywork / Dent / Dent	
6	Fender / Front Left	Bodywork / Dent / Dent	
7	Hood	Bodywork / Dent / Dent	
8	Steering Wheel / Front	Interior / Worn - out	

Vehicle Condition Imagery

Click Here For Larger Images

1. Bumper / Back
Paint / Scratch / Scuff -

2. Side Panel / Back Right
Paint / Scratch / Scuff -



3. Door / Back Right
Paint / Scratch / Scuff -

4. Fender / Front Right
Paint / Scratch / Scuff -



5. Tailgate
Bodywork / Dent / Dent -



6. Fender / Front Left
Bodywork / Dent / Dent -

Vehicle Condition Imagery

Click Here For Larger Images



7. Hood
Bodywork / Dent / Dent -



8. Steering Wheel / Front
Interior / Worn - out -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Alternator / Battery	✓
Power Steering Warning Light	✓	All - wheel Drive	✓
No Dashboard Lights	✓		

Engine

Engine Starts	✓	Engine Status / EML	!
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
AC / Heating System	✓		

Gearbox

Gear Box	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning	✓		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	NA		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide