MERCEDES-BENZ C-Klasse
C 220 d T 9G-TRONIC

VIN NO W1K2052141G077283

Registration Number 141G077283

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-02-01	3	2	105233 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
-	-	2021-01-22	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924110249
Inspection Date / Place	2025-09-24 / ARS Altmann AG Wolnzach	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1950
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	117
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Tow ball	Airbag Status	Anti-lock braking	Cruise control
Digital Radio	Remote adjusting wing mirrors	Reversing Camera	Satellite navigation
Central locking	LED Headlamps	Rear parking sensors	Trip Computer
Alloys wheels	Bluetooth telephone interface	Diesel particulate filter	Front parking sensors
Remote central locking	Roof rails	Stability control	Leather steering wheel
Radio			

Equipment Details

Tow Ball Type	Pivoted	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	16	Seat Heating	Front

Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage





	Component	Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Door / Front Left	Paint / Scratch / Scuff	
3	Pillar / Back Left	Bodywork / Dent / Dent	
4	Door / Back Left	Paint / Scratch / Scuff	
5	Side Panel / Back Left	Paint / Scratch / Scuff	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Tailgate	Paint / Scratch / Scuff	
8	Luggage Space Cover / Back	Interior / Scratched	
9	Door / Back Right	Paint / Scratch / Scuff	
10	Pillar / Back Right	Paint / Scratch / Scuff	
11	Door / Front Right	Paint / Scratch / Scuff	
12	Bumper / Front	Paint / Scratch / Scuff	

Vehicle Condition Imagery

Click Here For Larger Images

1. Bumper / Front
Paint / Scratch / Scuff -

2. Door / Front Left
Paint / Scratch / Scuff -

3. Pillar / Back Left
Bodywork / Dent / Dent -



4. Door / Back Left
Paint / Scratch / Scuff -

5. Side Panel / Back Left
Paint / Scratch / Scuff -

6. Bumper / Back
Paint / Scratch / Scuff -

Vehicle Condition Imagery

Click Here For Larger Images

7. Tailgate
Paint / Scratch / Scuff -

8. Luggage Space Cover / Back
Interior / Scratched -



9. Door / Back Right
Paint / Scratch / Scuff -

10. Pillar / Back Right
Paint / Scratch / Scuff -

11. Door / Front Right
Paint / Scratch / Scuff -

12. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓

Equipments Test

AC / Heating System	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		

✓ ***No troubles detected, good condition or correct tests, according to vehicle age and mileage***
! ***Damages or malfunction detected that requires repairs by the buyer***
NA ***Not applicable***
− ***Not tested***

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide