MERCEDES-BENZ C-Klasse
AMG C 43 Coupe 4Matic AMG Speedshift TCT 9G

VIN NO W1K2053641G089941

Registration Number 641G089941

BCA

MOT Date	**Number of Owners**	**Number of Keys**	**Odometer Reading**
⚠ 2025-05-01	👥 2	🔑 2	🕐 70051 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
🗓 -	🕐 -	🗓 2021-06-23	📖 Germany

Inspection Report Summary

|			
Customer	BCA Online	Report Number	P20250915141142
Inspection Date / Place	2025-09-15 / ARS Altmann AG Riedstadt	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	2996
Engine Size	3.0	No of Doors	2
Body Type	Coupe	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	4
Seat Covering Name	Anthrazit	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Equipment

|			
Tinted Glass	Trip Computer	Adaptivecruisecontrol	Alloys wheels
Anti-lock braking	Cruise control	Digitaldashboard	Heated wing mirrors
Remote adjusting wing mirrors	Reversing Camera	Split folding rear seats	Sunroof
Distancewarningsystem	Electrically folding wing mirrors	Laneassist	LED Headlamps
Rain sensitive windscreen wipers	Trafficsignrecognition	USB Socket	Airbag Status
Ambientlighting	Bluetooth telephone interface	Digital Radio	Front parking sensors
Parking Assistance	Remote central locking	Satellite navigation	Stability control
Central locking	Electrically adjustable seats	Emergencybrakeassist	Leather steering wheel
Radio	Rear parking sensors		

Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front
Sunroof Type	Opening Panoramic		

Wheels & Tyres

|			
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7
Extra Wheel - 1 Tyre Depth	7	Extra Wheel - 2 Tyre Depth	7
Extra Wheel - 3 Tyre Depth	7	Extra Wheel - 4 Tyre Depth	8

Cosmetic Damage

|	Component	Damage	Comments
1	Hood	Paint / Scratch / Scuff	
2	Bumper / Back	Paint / Scratch / Scuff	
3	Side Panel / Back Right	Paint / Scratch / Scuff	
4	Windshield / Front	Glass Break / Impact	
5	Door / Front Right	Paint / Poor Previous Repair	
6	Side Panel / Back Right	Paint / Poor Previous Repair	

1. Hood
Paint / Scratch / Scuff -

2. Bumper / Back
Paint / Scratch / Scuff -

3. Side Panel / Back Right
Paint / Scratch / Scuff -

4. Windshield / Front
Glass Break / Impact -

5. Door / Front Right
Paint / Poor Previous Repair -

6. Side Panel / Back Right
Paint / Poor Previous Repair -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	❗
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly ✅

Engine

Engine Noise	✅	The Gears Scratch / Skip / Abnormal Operation	✅
Fume Quantity	✅	Power Loss	✅

Brake

Brake System Anomaly ✅

General

Test Driven Status ✅

✅ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
❗ *Damages or malfunction detected that requires repairs by the buyer*
🆖 *Not applicable*
➖ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide