MERCEDES-BENZ E-Klasse
E 300 de 4Matic T 9G-TRONIC

VIN NO W1KZH1BB5PB099262

Registration Number B5PB099262

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	1	2	163768 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
2025-05-15	151308	2022-08-15	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250829142515
Inspection Date / Place	2025-08-29 / BCA Neuss	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1950
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables	Type 2	WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Tow ball	Alloys wheels	Anti-lock braking	Cruise control
Digital Radio	Enhanced speaker system	Massageseats	Remote central locking
Roof rails	Seatventilation	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors	Airbag Status	Ambientlighting
Bluetooth telephone interface	Diesel particulate filter	Digitaldashboard	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details

Tow Ball Type	Electronic	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18	Enhanced Speaker System	Burmester
Seat Heating	Front and Rear		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage





	Component	Damage	Comments
1	Rim / Back Right	Out of Bodywork / Scratch	
2	Mirror Repeater / Right	Glass Break	
3	Windshield / Front	Paint / Chipping	
4	Windshield / Front	Paint / Chipping	
5	Bumper / Front	Paint / Chipping	

Vehicle Condition Imagery

Click Here For Larger Images

1. Rim / Back Right
Out of Bodywork / Scratch -



2. Mirror Repeater / Right
Glass Break -

3. Windshield / Front
Paint / Chipping -

4. Windshield / Front
Paint / Chipping -

5. Bumper / Front
Paint / Chipping -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Diesel Particulate Filter Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	!
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		

✓ ***No troubles detected, good condition or correct tests, according to vehicle age and mileage***
! ***Damages or malfunction detected that requires repairs by the buyer***
NA ***Not applicable***
− ***Not tested***

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide