AUDI A6

A6 Avant 40 TDI quattro S tronic

VIN NO WAUZZZF24NN060963

Registration Number 24NN060963

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-07-01	1	2	168508 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
-	-	2022-07-04	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250908081437
Inspection Date / Place	2025-09-08 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Equipment

Tinted Glass	Alloys wheels	Anti-lock braking	Cruise control
Digital Radio	Enhanced speaker system	Heated wing mirrors	Remote central locking
Roof rails	Stability control	Electrically folding wing mirrors	Leather steering wheel
Radio	Airbag Status	Ambientlighting	Bluetooth telephone interface
Diesel particulate filter	Digitaldashboard	Front parking sensors	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors		

Equipment Details

Air Conditioning	Four Zone Climate Control	Alloy Wheel Size	18
Enhanced Speaker System	Bang & Olufsen	Seat Heating	Front

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage





	Component	Damage	Comments
1	Hood	Paint / Stone Chip	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Panel Filling / Front Left	Interior / Scratched	
6	Door / Back Left	Paint / Scratch / Scuff	
7	Pillar / Back Left	Paint / Scratch / Scuff	
8	Side Panel / Back Left	Bodywork / Dent / Dent	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Tailgate Upholstery / Back	Interior / Scratched	
11	Side Panel / Back Right	Paint / Scratch / Scuff	
12	Pillar / Back Right	Bodywork / Dent / Dent	

13	Door / Front Right	Paint / Scratch / Scuff
14	Steering Wheel / Front	Interior / Scratched
15	Bumper / Front	Bodywork / Breakage / Crack

Vehicle Condition Imagery

Click Here For Larger Images

1. Hood
Paint / Stone Chip -

2. Bumper / Front
Paint / Scratch / Scuff -

3. Bumper / Front
Paint / Scratch / Scuff -

4. Bumper / Front
Paint / Scratch / Scuff -



5. Panel Filling / Front Left
Interior / Scratched -

6. Door / Back Left
Paint / Scratch / Scuff -

Vehicle Condition Imagery

Click Here For Larger Images



7. Pillar / Back Left
Paint / Scratch / Scuff -



8. Side Panel / Back Left
Bodywork / Dent / Dent -

9. Bumper / Back
Paint / Scratch / Scuff -

10. Tailgate Upholstery / Back
Interior / Scratched -

11. Side Panel / Back Right
Paint / Scratch / Scuff -

12. Pillar / Back Right
Bodywork / Dent / Dent -

Vehicle Condition Imagery

Click Here For Larger Images

13. Door / Front Right
Paint / Scratch / Scuff -

14. Steering Wheel / Front
Interior / Scratched -

15. Bumper / Front
Bodywork / Breakage / Crack -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	Fume Quantity	✓
The Gears Scratch / Skip / Abnormal Operation	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		
Gearbox			
Automatic Shift	✓		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide