AUDI A4

A4 Avant 40 TDI quattro S tronic

VIN NO WAUZZZF47NA047987

Registration Number 47NA047987

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	1	2	104608 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
2022-08-26	1	2022-08-25	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250905112255
Inspection Date / Place	2025-09-05 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	anthrazit	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Tinted Glass	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Remote adjusting wing mirrors	Reversing Camera	Satellite navigation
Electrically folding wing mirrors	Leather steering wheel	Radio	Airbag Status
Anti-lock braking	Cruise control	Digital Radio	Heated wing mirrors
Remote central locking	Roof rails	Stability control	Electrictailgate
LED Headlamps	Rear parking sensors		

Equipment Details

Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	18
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage





	Component	Damage	Comments
1	Rocker Panel / Center Left	Bodywork / Breakage	
2	Bumper / Back	Paint / Scratch / Scuff	
3	Roof	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Hood	Paint / Scratch / Scuff	
6	Center Console	Interior / Scratched	

Vehicle Condition Imagery

Click Here For Larger Images



1. Rocker Panel / Center Left
Bodywork / Breakage -

2. Bumper / Back
Paint / Scratch / Scuff -

3. Roof
Paint / Scratch / Scuff -

4. Bumper / Front
Paint / Scratch / Scuff -



5. Hood
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Diesel Particulate Filter Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	!	Electric Windows	✓
Navigation System	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	!

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide