FORD Focus

Focus Turnier 1.0 EcoBoost Start-Stopp-System

VIN NO WF06XXGCC6EG56462

Registration Number CC6EG56462

MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	214556 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
2018-08-01	68567	2014-12-19	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250826141502
Inspection Date / Place	2025-08-26 / Dello Parchim	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	998
Engine Size	1.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	109
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images



Equipment

Trip Computer	Airbag Status	Enhanced speaker system	Remote adjusting wing mirrors
Stability control	Central locking	Emergencybrakeassist	Radio
USB Socket	Anti-lock braking	Heated wing mirrors	Split folding rear seats
CD Player	Distancewarningsystem	Leather steering wheel	

Equipment Details

Air Conditioning	Yes	Seat Heating	No

Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage





	Component	Damage	Comments
1	Door / Back Left	Bodywork / Dent / Dent	
2	Door / Back Left	Bodywork / Dent / Dent	
3	Fender / Front Right	Bodywork / Dent / Dent	

Vehicle Condition Imagery

Click Here For Larger Images

1. Door / Back Left
Bodywork / Dent / Dent -



2. Door / Back Left
Bodywork / Dent / Dent -

3. Fender / Front Right
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓		

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓

Gearbox

Gear Box	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Steering Wheel			
Steering | Noise / Anomaly	✓		
Clutch			
Clutch Functioning	✓		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	NA		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide