FORD Fiesta
Fiesta 1.0 EcoBoost S&S

VIN NO WF0FXXGAHFJS19167

Registration Number AHFJS19167

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-09-01	2	2	161405 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
2021-05-06	46015	2018-04-25	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250910111325
Inspection Date / Place	2025-09-10 / ARS Altmann AG Wolnzach	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	998
Engine Size	1.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	105
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images



Equipment

Airbag Status	Anti-lock braking	Remote adjusting wing mirrors	Satellite navigation
Central locking	Radio	Alloys wheels	Bluetooth telephone interface
Remote central locking	Stability control	Leather steering wheel	

Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage





	Component	Damage	Comments
1	Bumper / Front	Paint / Stone Chip	
2	Door / Front Left	Paint / Scratch / Scuff	
3	Side Panel / Back Left	Paint / Scratch / Scuff	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Door / Front Right	Paint / Scratch / Scuff	

Vehicle Condition Imagery

Click Here For Larger Images

1. Bumper / Front
Paint / Stone Chip -

2. Door / Front Left
Paint / Scratch / Scuff -



3. Side Panel / Back Left
Paint / Scratch / Scuff -

4. Bumper / Back
Paint / Scratch / Scuff -



5. Door / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓

Levels

Brakes Fluid	NA	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning	✓		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide