FORD Mondeo

Mondeo Turnier 2.0 EcoBoost Start-Stopp Autom.

VIN NO WF0FXXWPCFFD30967

Registration Number PCFFD30967

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-10-01	3	2	147978 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
-	-	2015-03-23	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250814161349
Inspection Date / Place	2025-08-14 / BCA Berlin	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	1999
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	174
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Tinted Glass	Alloys wheels	Cruise control	Front parking sensors
Remote central locking	Roof rails	Stability control	CD Player
Electrictailgate	Radio	Airbag Status	Anti-lock braking
Front fog lamps	Remote adjusting wing mirrors	Reversing Camera	Satellite navigation
Sunroof	Electrically folding wing mirrors	LED Headlamps	Rear parking sensors

Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front
Sunroof Type	Opening Panoramic		

Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6
Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage





	Component	Damage	Comments
1	Side Panel / Back Left	Paint / Scratch / Scuff	
2	Tailgate Upholstery / Back	Interior / Scratched	
3	Door / Back Right	Bodywork / Dent / Dent	
4	Windshield / Front	Paint / Chipping	
5	Fender / Front Left	Paint / Poor Previous Repair	
6	Side Panel / Back Right	Paint / Poor Previous Repair	
7	Door / Back Right	Paint / Poor Previous Repair	

Vehicle Condition Imagery

Click Here For Larger Images

1. Side Panel / Back Left
Paint / Scratch / Scuff -

2. Tailgate Upholstery / Back
Interior / Scratched -

3. Door / Back Right
Bodywork / Dent / Dent -



4. Windshield / Front
Paint / Chipping -

5. Fender / Front Left
Paint / Poor Previous Repair -

6. Side Panel / Back Right
Paint / Poor Previous Repair -

7. Door / Back Right
Paint / Poor Previous Repair -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	!
Other Equipments	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		

✓ ***No troubles detected, good condition or correct tests, according to vehicle age and mileage***
! ***Damages or malfunction detected that requires repairs by the buyer***
NA ***Not applicable***
− ***Not tested***

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide