# FORD Kuga
## Kuga 2.5 Duratec PHEV

VIN NO WF0FXXWPMHLE30518

Registration Number PMHLE30518

| MOT Date | Number of Owners | Number of Keys | Odometer Reading |
|---|---|---|---|
| 2026-06-01 | 1 | 2 | 75886 km |
| **Last Service** | **Last Service Mileage** | **First Registration Date** | **Country First Registered** |
| 2024-07-18 | 60437 | 2021-05-12 | Germany |

## Inspection Report Summary

| | | | |
|---|---|---|---|
| Customer | BCA Online | Report Number | P20250926120413 |
| Inspection Date / Place | 2025-09-26 / ARS Altmann AG Riedstadt | Cosmetic Grade | 3 |

## Vehicle Summary

| | | | |
|---|---|---|---|
| Vehicle Condition | Runner | VAT Type | Margin |
| Fuel Type | Plug - in Hybrid Electric Vehicle Petrol | Road Worthy | Yes |
| Colour | Grey | Engine Size (cc) | 2488 |
| Engine Size | 2.5 | No of Doors | 5 |
| Body Type | SUV | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Seat Covering Name | | Seat Covering | Synthetic Leather |
| Charging Cables | OUC + Type 2 | WLTP CO2 Emissions | |
| Gearbox Type | Automatic | | |

## Vehicle History & Documents

| | | | |
|---|---|---|---|
| Service Book Available | Computer Print Out Available | Next Service Mileage | km |
| Previous Usage | | Imported | No |
| Manufacturer Warrenty | | | |

## Vehicle Remarketing Imagery

Click Here For Larger Images

## Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images



## Equipment

| | | | |
|---|---|---|---|
| Tinted Glass | USB Socket | Alloys wheels | Bluetooth telephone interface |
| Digitaldashboard | Head up Display | Remote central locking | Satellite navigation |
| Electrically folding wing mirrors | Leather steering wheel | Radio | Trip Computer |
| Airbag Status | Anti-lock braking | Cruise control | Front parking sensors |
| Remote adjusting wing mirrors | Reversing Camera | Stability control | Electrictailgate |
| LED Headlamps | Rear parking sensors | | |

## Equipment Details

| | | | |
|---|---|---|---|
| Air Conditioning | Dual Zone Climate Control | Alloy Wheel Size | 18 |
| Extra Wheel / Tyre Set | Winter Tyres - Alloy | Seat Heating | Front |

## Wheels & Tyres

| | | | |
|---|---|---|---|
| Extra Wheel - 1 Tyre Depth | 5 | Extra Wheel - 2 Tyre Depth | 5 |
| Extra Wheel - 3 Tyre Depth | 5 | Extra Wheel - 4 Tyre Depth | 5 |
| Right Front Tyre Depth | 4 | Left Front Tyre Depth | 4 |
| Right Rear Tyre Depth | 4 | Left Rear Tyre Depth | 4 |

## Cosmetic Damage







| | Component | Damage | Comments |
|---|---|---|---|
| 1 | Hood | Paint / Stone Chip | |
| 2 | Bumper / Front | Paint / Scratch / Scuff | |
| 3 | Bumper / Front | Paint / Scratch / Scuff | |
| 4 | Bumper / Back | Paint / Scratch / Scuff | |
| 5 | Rear Window / Back | Glass Break / Scratch / Scratch | |
| 6 | Fender / Back Right | Bodywork / Dent / Dent | |
| 7 | Fender / Back Right | Bodywork / Dent / Dent | |

## Vehicle Condition Imagery

Click Here For Larger Images



1. Hood
Paint / Stone Chip -

2. Bumper / Front
Paint / Scratch / Scuff -

3. Bumper / Front
Paint / Scratch / Scuff -

4. Bumper / Back
Paint / Scratch / Scuff -



5. Rear Window / Back
Glass Break / Scratch / Scratch -



6. Fender / Back Right
Bodywork / Dent / Dent -

## Vehicle Condition Imagery

Click Here For Larger Images



7. Fender / Back Right
Bodywork / Dent / Dent -

## Mechanical Condition

### Engine

| | | | |
|---|---|---|---|
| Engine Starts | ✓ | Engine Status / EML | ✓ |
| Engine Leak Visible | ✓ | | |

### Control Lights

| | | | |
|---|---|---|---|
| ABS Warning Light | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light | ✓ | Oil Pressure Warning Light | ✓ |
| Brake Warning Light | ✓ | Power Steering Warning Light | ✓ |
| Alternator / Battery | ✓ | No Dashboard Lights | ✓ |
| Display Defect | ✓ | Service Light | ✓ |
| Tire Pressure Monitoring System | ✓ | | |

### Gearbox

| | | | |
|---|---|---|---|
| Gear Box | ✓ | | |

### Hybrid/EV

| | | | |
|---|---|---|---|
| Hybrid System Fault | ✓ | | |

### Equipments Test

| | | | |
|---|---|---|---|
| Other Equipments | ✓ | Central Locking | ✓ |
| Main & Spare Keys Functioning | ✓ | Electric Windows | ✓ |
| Navigation System | ✓ | Audio Equipment | ✓ |
| Parking Sensors / Cameras Functioning | ✓ | AC / Heating System | ✓ |

### Levels

| | | | |
|---|---|---|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |

## Test Drive Inspection

| | | | |
|---|---|---|---|
| **Engine** | | | |
| Engine Noise | ✓ | Fume Quantity | ✓ |
| Power Loss | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| **Brake** | | | |
| Brake System Anomaly | ✓ | | |
| **Steering Wheel** | | | |
| Steering \| Noise / Anomaly | ✓ | | |
| **General** | | | |
| Test Driven Status | ✓ | | |

✓ ***No troubles detected, good condition or correct tests, according to vehicle age and mileage***
! ***Damages or malfunction detected that requires repairs by the buyer***
NA ***Not applicable***
− ***Not tested***

## Disclaimer

*Please also note the "UserGuide condition report", which shows the scope of the vehicle description.* User Guide