MINI COUNTRYMAN

Mini Cooper D Countryman All4

VIN NO WMWYU110603E28293

Registration Number 0603E28293

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-10-01	1	2	183237 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
2024-10-28	163236	2017-11-22	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250825101110
Inspection Date / Place	2025-08-25 / BCA Oberndorf	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Sedan	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	127
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images



Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Trip Computer	Airbag Status	Ambientlighting	Auxiliary Socket
Diesel particulate filter	Remote adjusting wing mirrors	Roof rails	Stability control
Electrically folding wing mirrors	LED Headlamps	Rear parking sensors	USB Socket
Alloys wheels	Anti-lock braking	Bluetooth telephone interface	Front fog lamps
Remote central locking	Split folding rear seats	Central locking	Leather steering wheel
Radio			

Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Seat Heating	No		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage





	Component	Damage	Comments
1	Other	Anomalyon Element	
2	Bumper / Front	Paint / Scratch / Line	
3	Hood	Bodywork / Dent / Dent	
4	Rim / Front Left	Paint / Stone Chip	
5	Rim / Back Left	Out of Bodywork / Scratch	
6	Trunk Upholstery / Back	Interior / Scratched	
7	Wing Stick / Back Right	Paint / Scratch / Line	
8	Rim / Front Right	Paint / Stone Chip	

Vehicle Condition Imagery

Click Here For Larger Images

1.
Anomalyon Element -

2. Bumper / Front
Paint / Scratch / Line -

3. Hood
Bodywork / Dent / Dent -

4. Rim / Front Left
Paint / Stone Chip -



5. Rim / Back Left
Out of Bodywork / Scratch -

6. Trunk Upholstery / Back
Interior / Scratched -

Vehicle Condition Imagery

Click Here For Larger Images



7. Wing Stick / Back Right
Paint / Scratch / Line -

8. Rim / Front Right
Paint / Stone Chip -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓
Audio Equipment	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓	Flywheel Noise	✓
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning	✓	Clutch Pedal Low / High	✓
Clutch Abnormal	✓		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	Not Performed		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide