![DEKRA logo] DEKRA Automotive Solutions

Vehicle details

VIN	YV1LFBMVD M1718931	Brand	VOLVO	Maintenance date	-
Licence Plate	K7-14-KS	Model	XC90 T8 AWD Plug-in hybrid R-Design	Maintenance mileage	-
Registration date	08/01/2021	Year	2021	Exterior Color	Black Metallic
Odometer	101 499 km	Engine size	1969	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	7	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	21/11/2025	Inspection loc.	Dekra Ayvens

Generic equipment

Automated air-conditioning	✅
Cruise control	✅
GPS system	✅
7 seater	✅
Alloy wheel rims	✅
Automatic Gearbox	✅
Heating seats	✅
Electric seats	✅
Tow	✅
Metallic paint	✅
Central locking	✅
Electric windows	✅
4x4	✅
Mixed upholstery	✅
Side rails	✅
Park Distance Control	✅
Audio System	✅
Led lighting	✅

Removable element

Spare wheel kit	✅
Load cover	✅
Vehicle charger	✅
Wireless charger	❌

Technical Document

User manual	✅
Warranty booklet	✅
Spare key	✅
Remote key	✅
Sat Nav CD ROM Software	✅

![DEKRA - DEKRA Automotive Solutions]

![DEKRA]

Tyres

Continental 275/45/20 Summer 5.0 mm

Continental 275/45/20 Summer 5.0 mm

Continental 275/45/20 Summer 5.0 mm

Continental 275/45/20 Summer 5.0 mm

Exterior

2
Part	Alloy wheel 20"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3
Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5
Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

7
Part	Alloy wheel 20"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8
Part	Wing
Position	Back left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9
Part	Tailgate / Boot door
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10
Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

11
Part	Alloy wheel 20"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

12
Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

13
Part	Alloy wheel 20"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

15
Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

16
Part	Roof wind deflector
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

4

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

6

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

1

Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info

14

Part	Damage appraisal
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info