![DEKRA - DEKRA Automotive Solutions logo]

Vehicle details

VIN	ZFA250000 02N33835	Brand	FIAT	Maintenance date	-
Licence Plate	FR199CN	Model	DUCATO Pritsche 33 L2 120 MultiJet 88KW	Maintenance mileage	-
Registration date	07/09/2020	Year	1000	Exterior Color	White Solid
Odometer	96 007 km	Engine size	2287	interior Color	Black
Fuel	Diesel	Body Type	Dropside van	Next technical inspection	01/09/2026
Seats	-	Transmission	Manual	CO2	-
Doors	2	Gears	-		

Inspection Details

Inspection date	20/11/2025	Inspection loc.	Hödlmayr Logistics GmbH

Generic equipment

Manual air-conditioning	✔

Removable element

Technical Document

|	
User manual	✔
Log books	✔
Spare key	✔
Remote key	✔

Tyres

Winter kit

Falken 215/70/15 R Winter 6.5 mm

Falken 215/70/15 R Winter 6.6 mm

Vredestein 215/70/15 R Winter 4.1 mm

Vredestein 215/70/15 R Winter 4.0 mm

Exterior

1

Part	Windscreen
Position	-
Damages	Stone impact
Severity	Diameter (mm) > 10
Repair mode	Replace

2

Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

3

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

4

Part	Wing
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

5

Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

6

Part	Door
Position	Side left
Damages	Scratched
Severity	-
Repair mode	Repair

7

Part	Sill
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

9

Part	Door sill
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10

Part	Dropsides
Position	Back
Damages	Dented
Severity	-
Repair mode	For info

11

Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

12

Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

13

Part	Door sill
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

8

Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others

14

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks