

## POLESTAR 2 LONG RANGE DUAL MOTOR

### Vehicle information

|                      |            |                                 |                        |
|----------------------|------------|---------------------------------|------------------------|
| License plate        | JLA09C     | Inspected by                    | T.H.                   |
| Year model           | 2021       | Date of inspection              | 2025-10-24             |
| Manuf. year/month    | 2021-01    | City                            | Björkvik               |
| First day in traffic | 2021-06    | Keys                            | 2                      |
| Colour               | Svart      | Service book                    | Elektronisk servicebok |
| Mileage              | 135 610 km | Latest service                  | -                      |
| Fuel                 | EI (EV)    | Mileage at the latest service - |                        |
| Transmission         | Automat    | Summer tires                    | 20" alu-fälg 5/5/5/5   |
| Engine effect        | 300 kW     | Winter tires                    | saknas                 |

### Damages

| Location           | Damage             | Comments                                                                                   | Costs excluding VAT |
|--------------------|--------------------|--------------------------------------------------------------------------------------------|---------------------|
| Rims, Aluminum rim | Damage             |                                                                                            | 220 €               |
| Skärm , Front left | Liten buckla/Repor | Vänster sida anmälan finns Volvia 250511, köparen betalar självrisk                        | 430 €               |
| Door, Front left   | Repa/Repor         | Långa repor, Vänster sida anmälan finns Volvia 250511, köparen betalar självrisk           | -                   |
| Door, Rear left    | Liten buckla/Repor | Kraftiga repor, skrap, Vänster sida anmälan finns Volvia 250511, köparen betalar självrisk | -                   |
| Skärm , Rear left  | Repa/Repor         |                                                                                            | 260 €               |
| Bumper, Rear       | Repa/Repor         |                                                                                            | 260 €               |
| Boot lid, Boot lid | Repa/Repor         |                                                                                            | 150 €               |
| Skärm , Rear right | Repa/Repor         |                                                                                            | 260 €               |
| Door, Rear right   | Liten buckla/Repor |                                                                                            | 260 €               |
| Door, Front right  | Repa/Repor         |                                                                                            | 150 €               |
| Bumper, Front      | Repa/Repor         | Samt blåstrad                                                                              | 260 €               |
| Bonnet, Bonnet     | Liten buckla/Repor | Buckla samt blåstrad                                                                       | 290 €               |
| Glass, Windshield  | Stenskott/Spricka  | Blåstrad                                                                                   | -                   |
| Total excl. VAT    |                    |                                                                                            | 2 540 €             |

### Images

[See all images in large format](#)











































































