

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2025		Claim number				Code / Agency				Date accident 18/09/2025							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 18/09/2025		Date first survey 25/09/2025		Place POMEZIA		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) RENAULT MASTER FG TA L2 H2 T33 dCi 135 start MY23 furgone 135CV 4P								Plate GT514XX		Vin Chassis VF1MA000472850452				First Registration 29/03/2024							
Usage status NON CONOSCIUTO		Km 57842		Tyres % 75		Color BIANCO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0		Wheelbase								Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations										SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
										Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)	
1 620104124X		Front bumper								S				S				S			
1 260607867R		Headlight								L S				S				S			
1 768F30005R		Trim of rear mudguard rear part								R S				S				S			
1 768F30006R		Trim of rear mudguard rear part								R S				S				S			
1 963017417R		External electrically adjustable rear-view mirror								R S				S				S			
1 261603141R		Fanalino lat. retrovisore est. 16W								R S				S				S			
1 963020619R		External electrically adjustable rear-view mirror								L S				S				S			
1 261652475R		Fanalino lat. retrovisore est. 16W								L S				S				S			
1 997900002R		Tyre inflation compressor								S				S				S			
1 Codice Ricambio		Bomboletta gonfiaggio pneumatici								S				S				S			
1 668119349R		Sub-windscreen drip tray side trim								L S				S				S			
1 760325069R		Side rear wall								R L				L				L			
1 766106529R		Rear corner piece								R L				L				L			
1 801009976R		Front door								R L				L				L			
1 631013582R		Front mudguard								L L				L				L			

New for old value (N)	Remarks PNEUM INV. HANKOOK 225/65/16C VHL SPORCO E RILEV SEGNA LAZ SU QUADRO STRUM.: RIGENERARE FAP INUTILE E CONTROLLARE PLACCHETTE FRENO
-----------------------	---