

Inspection Protocol

TOYOTA YARIS HYBRID CVT, 116HK, 2021

Vehicle information

License plate	TLS06Y	Inspected by	S.V.
Year model	2021	Date of inspection	2025-10-24
Manuf. year/month	2021-04	City	Falkenberg
First day in traffic	2021-05	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	86 160 km	Latest service	-
Fuel	Bensin	Mileage at the latest service -	
Transmission	Automat	Summer tires	15" alu-fälg 4/4/4/4
Engine effect	85 kW	Winter tires	alu-fälg dubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Skärm , Rear right	Smart repair	Liten buckla	70 €
Skärm , Front right	Smart repair	Liten buckla	70 €
Bumper, Front	Smart repair		70 €
Bonnet, Bonnet	Smart repair		70 €
Glass, Windshield	Stenskott/Spricka	TLS06Y 250910, köpare betalar självrisk	220 €
Tak, Tak	Smart repair		70 €

Total excl. VAT	570 €
------------------------	--------------

Images

[See all images in large format](#)



















Skärm Höger bak Smart repair Liten buckla 1 000 kr



Skärm Höger fram Smart repair Liten buckla 1 000 kr



Stötfångare Fram Smart repair 1 000 kr



Motorhuv Motorhuv Smart repair 1 000 kr



Glas Vindruta Stenskott/Spricka TLS06Y 250910, köpare betalar självrisk 2 940 kr



Tak Tak Smart repair 1 000 kr





