

Inspection Protocol



CUPRA LEON SPORTSTOURER E-HYBRID

Vehicle information

License plate	AAJ04K	Inspected by	A.A.
Year model	2024	Date of inspection	2025-05-23
Manuf. year/month	2024-01	City	Björkvik
First day in traffic	2024-01	Keys	2
Colour	Grå	Service book	Elektronisk servicebok
Mileage	36 800 km	Latest service	2025-02-28
Fuel	Elhybrid	Mileage at the latest service	30 860 km
Transmission	DSG Sekventiell	Summer tires	19" alu-fälg 6/6/6/6
Engine effect	180 kW	Winter tires	alu-fälg odubbat 8/8/8/8

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Cargo scratches		180 €

Total excl. VAT	180 €
-----------------	-------

Images

[See all images in large format](#)







Avdelning 362 Verkstad, Upplands Väsby

FAKTURA
Datum 2025-02-28
Kund

Nr 26306488
Sida 1

Serviceprotokoll

SEAT S.A.

Ordernr 13336	Modellkod KU8CVY	Registreringsnr AAJ04K	Registrering 2024-03-22
Chassinummer VSSZZKL0RR063597	MMB DGEA	Mätarställning 30860	Servicerådgivare
Modellkod LEONSP1,4eHYBC LVZST180 ML9A6	VMB VBY	Årsmodell 2024	Datum 28.02.2025

Inspektion med oljebyte (fast)

Bilen invändigt

	Ok/genomförd	Inte ok	Ötgärdat
Kontrollera connect-tjänsterna och aktivera verkstadsläget	☒	☐	☐
Belysning fram och bak, blinkers, varningsblinkers, halvljus, varselljus, statiskt kurvlyjus och automatisk ljusstyrning (i förekommande fall): Kontrollera funktionen	☒	☐	☐
Oljebytesintervallindikering: Nollställa	☒	☐	☐











