

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	267208
License plate	1YKX086
Vehicle identification number	1C4BU0000LPL80816
Dossier	1802 114 362
Make	Jeep Reneg.1.3 T4 150 4x2 BL.S
Mileage	49025.00
First registration	24/09/2020
	13/01/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
63	Wing Front Left // Painting	N
67	Wing Front Left / Trim / Replace	N
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
19	Bumper Front / Lower Cover Not Painted / Replace	N
32	Front Bonnet // Painting	N
86	Door Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
146	Back Side / Reflector L / Replace	N
156	Rear Bonnet // Polish	Y
166	Roof / Antenna / Replace	N
187	Wing Rear Right / Trim / Replace	Y
197	Door Rear Right / Trim / Replace	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	Y


Damage Pictures



Wing Rear Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Rear Bonnet // Polish-scratch



Door Rear Left // Polish-scratch



Door Front Left // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Rear Left / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Polish-scratch



Rocker Panel Left // Smart Repair Medium-dent



Bumper Front / Lower Cover Not Painted / Replace-scratch + dent







Back Side / Reflector L / Replace-cracked



Roof / Antenna / Replace-missing



Front Bonnet // Painting-Chemical reaction



Interior Cleaning // Small-stain



Bumper Front // Repair & Painting-scratch + dent



Wing Front Left // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch