



JEEP Compass 2014 Diesel compass 2.2 crd North 136cv 2wd

VIN NO 1C4NJCGU1ED559392
Registration Number ET843WB



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-02-21	-	-	127811 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-02-18	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251003153722
Inspection Date / Place	2025-10-03 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	159

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Cruise control	Tyre Mobility Kit	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Trip Computer	Stability control


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	NEXEN NEXEN-N'FERA PRIMUS SU1	215/60//R17 - 96H / 3 mm
	NEXEN NEXEN-N'FERA PRIMUS SU1	215/60//R17 - 96H / 3 mm
	NEXEN NEXEN-N'FERA PRIMUS SU1	215/60//R17 - 96H / 3 mm
	NEXEN NEXEN-N'FERA PRIMUS SU1	215/60//R17 - 96H / 3 mm

Cosmetic Damage

25 Danni




3 Danni



Component		Damage	Comments
1	Seat Cushion / Front Left	Interior / Ripped	
2	Steering Wheel / Front	Interior / Worn - out	
3	Windshield / Front	Glass Break / Impact	
4	Hood	Bodywork / Dent / Hail Area	
5	Hood	Bodywork / Dent	
6	Bumper / Front	Bodywork / Dent	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Fender / Front Left	Bodywork / Dent	
9	Mirror Shell / Front Left	Paint / Scratch / Line	
10	Door / Front Left	Paint / Scratch / Line	
11	Door / Front Left	Paint / Scratch / Line	
12	Door / Back Left	Paint / Scratch / Line	


13	Door / Back Left	Bodywork / Dent
14	Rim / Back Left	Out of Bodywork / Scratch
15	Panel Filling / Back Left	Interior / Broken
16	Fender / Back Left	Bodywork / Dent
17	Pillar / Front Left	Bodywork / Dent
18	Bumper / Back	Bodywork / Dent
19	Tailgate	Bodywork / Dent
20	Fender / Back Right	Bodywork / Dent
21	Fender / Back Right	Bodywork / Poor Previous Repair
22	Rim / Back Right	Out of Bodywork / Scratch
23	Door / Back Right	Paint / Scratch / Line
24	Door / Front Right	Paint / Scratch / Line
25	Fender / Front Right	Paint / Scratch / Line
26	Rim / Front Right	Out of Bodywork / Scratch
27	Pillar / Front Right	Bodywork / Dent
28	Roof	Bodywork / Dent / Hail Area



1. Seat Cushion / Front Left
Interior / Ripped -



2. Steering Wheel / Front
Interior / Worn - out -



3. Windshield / Front
Glass Break / Impact -



4. Hood
Bodywork / Dent / Hail Area -



5. Hood
Bodywork / Dent -




6. Bumper / Front
Bodywork / Dent -



7. Rim / Front Left
Out of Bodywork / Scratch -



8. Fender / Front Left
Bodywork / Dent -



9. Mirror Shell / Front Left
Paint / Scratch / Line -



10. Door / Front Left
Paint / Scratch / Line -



11. Door / Front Left
Paint / Scratch / Line -



12. Door / Back Left
Paint / Scratch / Line -



13. Door / Back Left
Bodywork / Dent -



14. Rim / Back Left
Out of Bodywork / Scratch -



15. Panel Filling / Back Left
Interior / Broken -



16. Fender / Back Left
Bodywork / Dent -



17. Pillar / Front Left
Bodywork / Dent -



18. Bumper / Back
Bodywork / Dent -



19. Tailgate
Bodywork / Dent -



20. Fender / Back Right
Bodywork / Dent -



21. Fender / Back Right
Bodywork / Poor Previous Repair -



22. Rim / Back Right
Out of Bodywork / Scratch -



23. Door / Back Right
Paint / Scratch / Line -



24. Door / Front Right
Paint / Scratch / Line -




25. Fender / Front Right
Paint / Scratch / Line -



26. Rim / Front Right
Out of Bodywork / Scratch -



27. Pillar / Front Right
Bodywork / Dent -



28. Roof
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Suspension	!
Steering	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

⊠ Not tested