

### JEEP Cherokee Cherokee 2.0 Multijet Active Drive I Automatik



VIN NO 1C4PJMDYXFW622890 Registration Number YXFW622890

MOT Date

★ 2026-11-01

Last Camilas

Last Service

**=**-

**Number of Owners** 

3

Last Service Mileage

**2** 

Number of Keys

**2**2

First Registration Date

**2**015-02-23

**Odometer Reading** 

**1**08681 km

**Country First Registered** 

Germany

### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250917122259
Inspection Date / Place	2025-09-17 / BCA Berlin	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	1956
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Black	Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	154
Gearbox Type	Automatic		

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			













































## Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Diesel particulate filter
Front parking sensors	Remote central locking	Roof rails	Stability control
Electrically folding wing mirrors	Radio	Tow ball	Alloys wheels
Cruise control	Front fog lamps	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Xenon headlamps	Electrictailgate	Rear parking sensors


## **Equipment Details**

Tow Ball Type	Detachable	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18		

## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	6
Right Rear Tyre Depth	5	Left Rear Tyre Depth	4

### Cosmetic Damage



	Component	Damage	Comments
1	Hood	Bodywork / Breakage / Crack	
2	Hood	Paint / Corrosion	
3	Door / Back Left	Paint / Scratch / Scuff	
4	Bumper / Back	Paint / Scratch / Scuff	



1. Hood Bodywork / Breakage / Crack -

2. Hood Paint / Corrosion -



3. Door / Back Left Paint / Scratch / Scuff -

4. Bumper / Back Paint / Scratch / Scuff -

#### **Mechanical Condition**

Control Lights			
Display Defect	•	ABS Warning Light	•
ESP Fault/Traction Control Malfunction Light	<b>⊘</b>	Airbag Warning Light	<b>⊘</b>
Oil Pressure Warning Light	<b>⊘</b>	Brake Warning Light	<b>⊘</b>
Alternator / Battery	•	No Dashboard Lights	•
Power Steering Warning Light	<b>⊘</b>	Tire Pressure Monitoring System	<b>⊘</b>
Equipments Test			
Main & Spare Keys Functioning	<b>Ø</b>	Electric Windows	<b>⊘</b>
Navigation System	<b>⊘</b>	Audio Equipment	<b>⊘</b>
Parking Sensors / Cameras Functioning	•	AC / Heating System	•
Other Equipments	<b>⊘</b>		
Engine			
Engine Status / EML	<b>②</b>	Engine Leak Visible	<b>②</b>
Engine Starts	•		
Levels			
Brakes Fluid	•	Coolant Fluid	<b>⊘</b>

#### **Test Drive Inspection**

description.

# Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

**User Guide**