



JEEP Grand Cherokee

Grand Cherokee 3.0l Multijet

VIN NO 1C4RJFBM9DC577346
Registration Number M9DC577346



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-12-01	3	1	182441 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2012-12-14	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925101056
Inspection Date / Place	2025-09-25 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	No
Colour	Black	Engine Size (cc)	2987
Engine Size	3.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	218
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

[Click Here For Larger Images](#)









Equipment

Tinted Glass	USB Socket	Alloys wheels	Blindspotassist
Cruise control	Front fog lamps	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Split folding rear seats	Sunroof	CD Player
Electrically adjustable seats	Electrictailgate	Radio	Tow ball
Airbag Status	Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Remote central locking	Roof rails	Seatventilation
Stability control	Xenon headlamps	Central locking	Electrically folding wing mirrors
Leather steering wheel	Rear parking sensors		

Equipment Details


Tow Ball Type	Static	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18	Extra Wheel / Tyre Set	Summer Tyres - Alloy
Seat Heating	Front and Rear	Sunroof Type	Opening Panoramic

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

14 Schäden




4 Schäden



Component		Damage	Comments
1	Other	Anomalyon Element	
2	Windshield / Front	Glass Break	
3	Blade/spoiler / Front	Bodywork / Breakage / Crack	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Hood	Bodywork / Dent / Dent	
6	Hood	Paint / Scratch / Line	
7	Roof	Bodywork / Dent / Dent	
8	Other	Interior / Broken	
9	Steering Wheel / Front	Interior / Scratched	
10	Seat / Front Left	Interior / Scratched	
11	Door / Back Left	Bodywork / Dent / Dent	
12	Bumper / Back	Paint / Scratch / Scuff	

13	Fender / Back Left	Paint / Scratch / Line
14	Trunk Upholstery / Back	Interior / Scratched
15	Door / Back Right	Bodywork / Dent / Dent
16	Door / Front Right	Paint / Scratch / Line
17	Other	Paint / Scratch / Scuff
18	Corner Bumper / Back Left	Bodywork / Breakage / Hole



1.
Anomaly Element -




2. Windshield / Front
Glass Break -



3. Blade/spoiler / Front
Bodywork / Breakage / Crack -




4. Bumper / Front
Paint / Scratch / Scuff -



5. Hood
Bodywork / Dent / Dent -



6. Hood
Paint / Scratch / Line -



7. Roof
Bodywork / Dent / Dent -



8.
Interior / Broken -



9. Steering Wheel / Front
Interior / Scratched -



10. Seat / Front Left
Interior / Scratched -




11. Door / Back Left
Bodywork / Dent / Dent -



12. Bumper / Back
Paint / Scratch / Scuff -



13. Fender / Back Left
Paint / Scratch / Line -



14. Trunk Upholstery / Back
Interior / Scratched -



15. Door / Back Right
Bodywork / Dent / Dent -



16. Door / Front Right
Paint / Scratch / Line -



17.
Paint / Scratch / Scuff -



18. Corner Bumper / Back Left
Bodywork / Breakage / Hole -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)