



CHEVROLET Corvette

Corvette Z06 Cabriolet 5.5 V8 3LZ

VIN NO 1G1Y92D30R5602706
Registration Number 30R5602706



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2028-08-01	1	2	34 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2025-08-12	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250912094955
Inspection Date / Place	2025-09-12 / BCA Neuss	Cosmetic Grade	1


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	No
Colour	Red	Engine Size (cc)	5460
Engine Size	5.5	No of Doors	2
Body Type	Convertible	Drive Train	Rear
Seat Colour		No of Seats	2
Seat Covering Name	Schwarz/ rot	Seat Covering	Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Cruise control	Digitaldashboard
Head up Display	Remote central locking	Seatventilation	Electrically folding wing mirrors
LED Headlamps	Rear parking sensors	Alloys wheels	Bluetooth telephone interface
Digital Radio	Enhanced speaker system	Remote adjusting wing mirrors	Reversing Camera
Stability control	Leather steering wheel	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	20
Enhanced Speaker System	Bose	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	1	Left Front Tyre Depth	1
Right Rear Tyre Depth	1	Left Rear Tyre Depth	1

Cosmetic Damage


1 Schäden



0 Schäden



Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	



1. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)