



CHEVROLET Corvette
Corvette Stingray Cabriolet 3LT 6.2 V8
Automatik

VIN NO 1G1Y93D48R5121679
Registration Number 48R5121679



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2028-08-01	1	2	23 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2025-08-11	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250917142152
Inspection Date / Place	2025-09-17 / BCA Neuss	Cosmetic Grade	1


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Orange	Engine Size (cc)	6162
Engine Size	6.2	No of Doors	3
Body Type	Convertible	Drive Train	Rear
Seat Colour		No of Seats	2
Seat Covering Name	Schwarz	Seat Covering	Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		


Vehicle History & Documents

Service Book Available	First Service not yet due	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

USB Socket	Alloys wheels	Anti-lock braking	Blindspotassist
Cruise control	Digitaldashboard	Head up Display	Remote central locking
Seatventilation	Electrically adjustable seats	Emergencybrakeassist	LED Headlamps
Rear parking sensors	Airbag Status	AndroidAuto	AppleCarPlay
Bluetooth telephone interface	Digital Radio	Enhanced speaker system	Remote adjusting wing mirrors
Reversing Camera	Stability control	Electrically folding wing mirrors	Leather steering wheel
Radio			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Enhanced Speaker System	Bose	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

Schäden



Schäden



Component	Damage	Comments
-----------	--------	----------

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	NA
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	NA
--------------	---	---------------	----

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)