



# FORD Edge

## Edge 2.0 EcoBlue Bi-Turbo 4x4 Aut.

VIN NO 2FMTK4K33KBC04181  
Registration Number 33KBC04181



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-01-01	2	2	59561 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2019-08-12	Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250917091744
Inspection Date / Place	2025-09-17 / BCA Berlin	Cosmetic Grade	1

### Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Unknown
Colour	White	Engine Size (cc)	1997
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	169
Gearbox Type	Automatic		


### Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	Alloys wheels	Cruise control	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	CD Player
Electrictailgate	Radio	Airbag Status	Anti-lock braking
Front fog lamps	Heated windscreen	Remote central locking	Roof rails
Stability control	Electrically folding wing mirrors	LED Headlamps	Rear parking sensors

Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Seat Heating	Front and Rear		


Wheels & Tyres

Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	4	Left Rear Tyre Depth	5



Cosmetic Damage


3 Schäden



0 Schäden




Component	Damage	Comments
1 Side Window / Front Left	Glass Break / Scratch / Scratch	
2 Rim / Front Right	Out of Bodywork / Scratch	
3 Windshield / Front	Paint / Chipping	



1. Side Window / Front Left  
Glass Break / Scratch / Scratch -



2. Rim / Front Right  
Out of Bodywork / Scratch -



3. Windshield / Front  
Paint / Chipping -

## Mechanical Condition

### Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



## Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

## Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)