

XR-920-T Jeep Compass 1.4 MultiAir 103kW Longitude

|        |                                                                                                                                    |       |            |          |       |
|--------|------------------------------------------------------------------------------------------------------------------------------------|-------|------------|----------|-------|
| Dealer | WITTEBRUG FOREPARK RHONE te 'S-GRAVENHAGE<br>Onh 15.000 Km<br>Koel-/verw systAirco Reinigen                                        | Datum | 04/09/2020 | Km stand | 11470 |
| Dealer | WITTEBRUG FOREPARK RHONE te 'S-GRAVENHAGE<br>Onh 30.000 Km                                                                         | Datum | 26/08/2021 | Km stand | 20687 |
| Dealer | WITTEBRUG - FOREPARK DONAU te 'S-GRAVENHAGE<br>Electr. Compon.Afstandbedienin                                                      | Datum | 12/11/2021 | Km stand | 24665 |
| Dealer | WITTEBRUG - FOREPARK DONAU te 'S-GRAVENHAGE<br>Onh 45.000 Km                                                                       | Datum | 01/08/2022 | Km stand | 28707 |
| Dealer | WITTEBRUG - FOREPARK DONAU te 'S-GRAVENHAGE<br>APK Zonder beurt<br>Verlichting Diverse lampjes<br>225/60 R17 99V<br>225/60 R17 99V | Datum | 09/01/2023 | Km stand | 33322 |
| Dealer | WITTEBRUG - FOREPARK DONAU te 'S-GRAVENHAGE<br>Onh 60.000 Km<br>Remmen Remvloeistof<br>Ruitenwiss.blad V                           | Datum | 05/12/2023 | Km stand | 48236 |
| Dealer | WITTEBRUG - YPENBURG te 'S-GRAVENHAGE<br>Onh 75.000 Km<br>APK icm beurt<br>Ruitewiss.blad A                                        | Datum | 02/12/2024 | Km stand | 65222 |

XR-920-T Jeep Compass 1.4 MultiAir 103kW Longitude

| Schadedatum | Oorzaak       | Schade aan<br>derden | Verhaalbaar | Aard schade       |
|-------------|---------------|----------------------|-------------|-------------------|
| 12/14/2019  | Storm         | Nee                  | Nee         | Rechterzijde      |
| 06/11/2020  | Obstakel      | Nee                  | Nee         | Linkerachterzijde |
| 07/23/2024  | Inleverschade | Nee                  | Nee         | Achterklep        |
| 07/23/2024  | Inleverschade | Nee                  | Nee         | Sleutel/zender    |