



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 21/06/2024	LOCALITA' LANZA REPAIR CENTER SRL , Strada Per Piccoli 3, 72100, BRINDISI (BR)																						
VEICOLO (MARCA - MODELLO - VERSIONE) JEEP COMPASS 2.0 MJet 103kW Limited 4WD auto Sport utility vehicle 5-doo					TARGA FR505DR		TELAIO 3C4NJDCY6JT351561		1ª IMMATRICOLAZ. 30/05/2018														
KM. 92860	COLORE. Jazz Blue			TIPO SMALTO METALL/DOPPIO																			
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa											
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO														
	Revisione ministeriale									64,77		64,77											
	Seconda chiave mancante																						
1935	#PRM# Parafango ant. SX																						
5003	#PRM# Paraurti ant. parte sup. Premium p/sens.parc																						
1935	Parafango ant. DX	L	0,80	L	0,70	L	1,20																
2168	Porta ant. DX	L	1,30			L	1,60																
2187	Porta post. DX	M	1,20			M	1,80																
3883	Ossatura vani porte con parafango post. DX	L	1,20			L	1,50																
5507	#PRM# Paraurti post. p/sup. P/sensori parcheggio																						
2168	#PRM# Porta ant. SX																						
2187	Porta post. SX	L	1,10	L	1,20	L	1,70																
TOTALE TEMPI												SR	5,60	LA	1,90	VE	7,80	ME	0,00	TOTALE RICAMBI			64,77
ORE SUPPLEMENTO DOPPIO STRATO 15 %		1,17	ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE		0,90	ORE AGGIUNTIVE PER VERNICIATURA		1,60	TOTALE ORE SUPPLEMENTARI		3,67	TOTALE ORE VERNICIATURA		11,47									
NOTE										RICAMBI		64,77											
Pneumatico ant dx - Bridgestone - 225/55/18 - multistagionale - 7 mm										MATER. DI CONSUMO		137,64											
Pneumatico ant sx - Bridgestone - 225/55/18 - multistagionale - 7 mm										ORE 11,47 €/ORA 12,00													
Pneumatico post dx - Bridgestone - 225/55/18 - multistagionale - 8 mm										USO DIME		0,00											
Pneumatico post sx - Bridgestone - 225/55/18 - multistagionale - 7 mm										SMALTIMENTO RIFIUTI		9,26											
Veicolo sporco esternamente, Periziato con tempo sereno										MANODOPERA CARR.		569,10											
										ORE 18,97 €/ORA 30,00													
										MANODOPERA MECC.		0,00											
										ORE 0,00 €/ORA 30,00													
										IMPONIBILE		780,77											
										IVA		171,77											
										TOTALE COMPLESSIVO		952,54											
CODICE PERITO 88	FIRMA			RUOLO N. 0000			FERMO TECNICO GIORNI			3	FOGLIO 1												

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 21/06/2024	LOCATION LANZA REPAIR CENTER SRL , Strada Per Piccoli 3, 72100, BRINDISI (BR)										
VEHICLE (BRAND - MODEL - VERSION) JEEP COMPASS 2.0 MJet 103kW Limited 4WD auto Sport utility vehicle 5-doo						PLATE FR505DR		CHASSIS 3C4NJDCY6JT351561		1st REGISTRATION. 30/05/2018	
KM. 92860	COLOR. Jazz blue			ENAMEL TYPE Metall/doppio							
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME		
	Periodic technical inspection									64,77	64,77
	Second key missing										
1935	#PRM# Front fender Sx										
5003	#PRM# Paraurti front part sup. premium p/sens.parc										
1935	Front fender Dx	L	0,80	L	0,70	L	1,20				
2168	Front door Dx	L	1,30			L	1,60				
2187	Rear door Dx	M	1,20			M	1,80				
3883	Door perimeter substructure complete with rear fen Dx	L	1,20			L	1,50				
5507	#PRM# Paraurti rear p/sup. p/sensori parking area										
2168	#PRM# Front door Sx										
2187	Rear door Sx	L	1,10	L	1,20	L	1,70				
TOTAL TIMES		SR 5,60		LA 1,90		VE 7,80		ME 0,00		TOTAL SPARE PARTS 64,77	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 1,17		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 0,90		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 3,67		TOTAL PAINTING HOURS 11,47			
NOTE Right front tire - Bridgestone - 225/55/18 - Multistagionale - 7 mm Left front tire - Bridgestone - 225/55/18 - Multistagionale - 7 mm Right rear tire - Bridgestone - 225/55/18 - Multistagionale - 8 mm Left rear tire - Bridgestone - 225/55/18 - Multistagionale - 7 mm Veicolo sporco esternamente , Appraised in clear weather								SPARE PARTS		64,77	
								MATER. CONSUMPTION HOURS 11,47€/HOUR 12,00		137,64	
								USE TEMPLATES		0,00	
								WASTING DISPOSAL		9,26	
								LABOR CARR. HOURS 18,97€/HOUR 30,00		569,10	
								LABOR MECH. HOURS 0,00 €/HOUR 30,00		0,00	
								TAXABLE		780,77	
								VAT		171,77	
								TOTAL		952,54	
EXPERT CODE 88	SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 3			SHEET 1		

Legend
 Ff: forfait Prm: reminder De: lack of execution Gr: hail Mac: stained Nu: normal wear Srg: stickers