



FIAT Freemont Diesel

freemont 2.0 mjt 16v Urban 140cv

VIN NO 3C4PFABY2CT172611
Registration Number EH951HB



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-04-16	-	-	301327 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-12-12	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251010101051
Inspection Date / Place	2025-10-10 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1956
Engine Size	2.0	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Black	No of Seats	7
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	169

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Alloys wheels	Electrically folding wing mirrors	Remote adjusting wing mirrors
Cruise control	Trip Computer	Power assisted steering	Digital Radio
Volante multifuncion	Remote central locking	Tow ball	Stability control

Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	PIRELLI PIRELLI-CINTURATO ALLSEASON	225/65//R17 - 106V / 3 mm
	PIRELLI PIRELLI-CINTURATO ALLSEASON	225/65//R17 - 106V / 3 mm
	PIRELLI PIRELLI-CINTURATO ALLSEASON	225/65//R17 - 106V / 2 mm
	PIRELLI PIRELLI-CINTURATO ALLSEASON	225/65//R17 - 106V / 2 mm

Cosmetic Damage



Component		Damage	Comments
1	Roof Upholstery	Interior / Scratched	
2	Dashboard / Front	Interior / Worn - out	
3	Windshield / Front	Glass Break / Impact	
4	Tailgate Upholstery / Back	Interior / Scratched	
5	Trunk Upholstery / Back	Interior / Scratched	
6	Cabin	Interior / Worn - out	
7	Grille / Front	Bodywork / Breakage	
8	Fender / Front Right	Bodywork / Poor Previous Repair	
9	Steering Wheel / Front	Interior / Worn - out	
10	Hood	Bodywork / Dent / Hail Area	
11	Roof	Bodywork / Dent / Hail Area	
12	Door / Back Left	Bodywork / Dent	

13	Pillar / Front Right	Bodywork / Dent / Hail Area
14	Pillar / Front Left	Bodywork / Dent / Hail Area
15	Bumper / Front	Bodywork / Breakage
16	Seat / Front Left	Interior / Broken
17	Bumper / Back	Bodywork / Dent
18	Seat / Front Right	Interior / Broken
19	Door / Front Right	Paint / Scratch / Line
20	Floor Carpet	Interior / Dirty
21	Fender / Back Left	Bodywork / Dent
22	Door / Back Right	Bodywork / Dent
23	Fender / Front Left	Paint / Chipping
24	Rim / Front Left	Out of Bodywork / Scratch
25	Bumper / Front	Bodywork / Breakage
26	Tailgate	Paint / Scratch / Line
27	Rim / Back Left	Out of Bodywork / Scratch
28	Rim / Back Right	Out of Bodywork / Scratch
29	Wing Repeater / Left	Bodywork / Breakage
30	Dashboard / Front	Interior / Worn - out
31	Door / Front Left	Paint / Scratch / Line
32	Towing Ring Hatches / Back	Missing Part
33	Mirror Shell / Front Left	Paint / Scratch / Line
34	Mirror Shell / Front Right	Paint / Scratch / Line
35	Fog Light / Back Right	Bodywork / Breakage
36	Fender / Back Right	Bodywork / Dent
37	Fog Light / Back Left	Glass Break
38	Dashboard / Front	Interior / Warning Light ON



1. Roof Upholstery
Interior / Scratched -



2. Dashboard / Front
Interior / Worn - out -



3. Windshield / Front
Glass Break / Impact -



4. Tailgate Upholstery / Back
Interior / Scratched -



5. Trunk Upholstery / Back
Interior / Scratched -



6. Cabin
Interior / Worn - out -




7. Grille / Front
Bodywork / Breakage -



8. Fender / Front Right
Bodywork / Poor Previous Repair -




9. Steering Wheel / Front
Interior / Worn - out -



10. Hood
Bodywork / Dent / Hail Area -



11. Roof
Bodywork / Dent / Hail Area -



12. Door / Back Left
Bodywork / Dent -



13. Pillar / Front Right
Bodywork / Dent / Hail Area -



14. Pillar / Front Left
Bodywork / Dent / Hail Area -



15. Bumper / Front
Bodywork / Breakage -



16. Seat / Front Left
Interior / Broken -



17. Bumper / Back
Bodywork / Dent -



18. Seat / Front Right
Interior / Broken -



19. Door / Front Right
Paint / Scratch / Line -



20. Floor Carpet
Interior / Dirty -



21. Fender / Back Left
Bodywork / Dent -



22. Door / Back Right
Bodywork / Dent -



23. Fender / Front Left
Paint / Chipping -



24. Rim / Front Left
Out of Bodywork / Scratch -



25. Bumper / Front
Bodywork / Breakage -



26. Tailgate
Paint / Scratch / Line -



27. Rim / Back Left
Out of Bodywork / Scratch -



28. Rim / Back Right
Out of Bodywork / Scratch -



29. Wing Repeater / Left
Bodywork / Breakage -



30. Dashboard / Front
Interior / Worn - out -



31. Door / Front Left
Paint / Scratch / Line -



32. Towing Ring Hatches / Back
Missing Part -



33. Mirror Shell / Front Left
Paint / Scratch / Line -



34. Mirror Shell / Front Right
Paint / Scratch / Line -



35. Fog Light / Back Right
Bodywork / Breakage -



36. Fender / Back Right
Bodywork / Dent -



37. Fog Light / Back Left
Glass Break -



38. Dashboard / Front
Interior / Warning Light ON -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested