



Tesla 3: H819SV

Vinnumber:	5YJ3E7EA6LF671722	Versionname:	Model 3 50kWh Standard Range Plus automaat
First Registrationdate:	6/05/2020	Fiscalpower:	
Expertise Mileage:	69210	Power Kw:	211
Bodytype:		Body colour:	Solid Black
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	1006
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Panoramic roof
Windows electric F		Central consol F
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

235/45/18/98 Y			
Winter tyres:	Fr.L.	Vredestein: 5,5 mm	Fr.R.
	Re.L.	Vredestein: 4,5 mm	Re.R.
			Vredestein: 6 mm
			Vredestein: 5,5 mm
Tyre profile depth FL			5.5
Tyre profile depth FR			6.0
Tyre profile depth RL			4.5
Tyre profile depth RR			5.5
Tyre size FL			235/45 R 18 98 Y
Tyre size FR			235/45 R 18 98 Y
Tyre size RL			235/45 R 18 98 Y
Tyre size RR			235/45 R 18 98 Y
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			2480
Tyre make FR			2480
Tyre make RL			2480
Tyre make RR			2480

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Wing FL, Dent(s), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)




Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (partial)



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Stone chip(s), Repair and paint (complete)



Panoramic roof, Crack, Replace

