



TESLA MODEL 3: FV-555-GR

Vinnumber:	5YJ3E7EB6MF832757	Versionname:	
First Registrationdate:	23/11/2020	Fiscalpower:	
Expertise Mileage:	37775	Power Kw:	
Bodytype:	Berline	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4x4	Interior colour:	Black
Fueltype:	Electric	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total:	2	Rear view camera
Number keys remote:	0	
GPS big screen color:		

Degree of wear

235/45/18/98 Y			
Summer tyres:	Fr.L.	Michelin: 60%	Fr.R.
	Re.L.	Michelin: 75%	Re.R.
			Michelin: 65%
Tyre profile depth FL			4.4
Tyre profile depth FR			4.4
Tyre profile depth RL			3.5
Tyre profile depth RR			3.9
Tyre size FL			235/45 R 18 98 Y
Tyre size FR			235/45 R 18 98 Y
Tyre size RL			235/45 R 18 98 Y
Tyre size RR			235/45 R 18 98 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Tyres, No damage, Acceptable



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace




Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Wing RL, Scratch(es), Polish



Bumper F, Deformed / Strained, Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Rubber seal for boot lid, Tear, Replace



Rear bulkhead lining, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Acceptable

