



Tesla 3: K058FT

Vinnnummer:	5YJ3E7EB6MF847629	Versionname:	Model 3 75kWh Long-Range AWD automaat
First Registrationdate:	19/12/2020	Fiscalpower:	
Expertise Mileage:	48911	Power Kw:	335
Bodytype:		Body colour:	Midnight Silver Metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	690
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Panoramic roof
Windows electric F		Central consol F
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

235/40/19/96 W				
Summer tyres:	Fr.L.	Vredestein: 6,5 mm	Fr.R.	Vredestein: 6,8 mm
	Re.L.	Hankook: 6,9 mm	Re.R.	Hankook: 6 mm
Tyre profile depth FL				6.5
Tyre profile depth FR				6.8
Tyre profile depth RL				6.9
Tyre profile depth RR				6.0
Tyre size FL				235/40 R 19 096 W
Tyre size FR				235/40 R 19 096 W
Tyre size RL				235/40 R 19 096 W
Tyre size RR				235/40 R 19 096 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Interior, Dirty, Cleaning





Tyre RL, Flat, Replace




Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Tyre RR, Tear, Replace



Outside rear-view mirror housing R, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)



Tyre FL, Tear, Replace



Tyre FR, Tear, Replace

