



### Tesla 3: J658HN

Vinnnummer:	5YJ3E7EC2LF754355	Versionname:	Model 3 Dual Motor 75kWh AWD Long Range Performance automaat
First Registrationdate:	14/08/2020	Fiscalpower:	358
Expertise Mileage:	178405	Power Kw:	
Bodytype:		Body colour:	Midnight Silver Metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	1129
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

### Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Panoramic roof
Windows electric F		Central consol F
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

### Degree of wear

235/35/20/92 Y				
Summer tyres:	Fr.L.	Goodyear: 6,1 mm	Fr.R.	Goodyear: 5,5 mm
	Re.L.	Michelin: 3,5 mm	Re.R.	Michelin: 4,2 mm
Tyre profile depth FL				6.1
Tyre profile depth FR				5.5
Tyre profile depth RL				3.5
Tyre profile depth RR				4.2
Tyre size FL				235/35 ZR 20 092 Y
Tyre size FR				235/35 ZR 20 092 Y
Tyre size RL				235/35 ZR 20 092 Y
Tyre size RR				235/35 ZR 20 092 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				261
Tyre make RR				261

### Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Roof liner, Stain, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Polish



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)

