



Tesla Model X: 1XRS031

Vinnnumber:	5YJXCCE28LF241148	Versionname:	
First Registrationdate:	25/03/2020	Fiscalpower:	
Expertise Mileage:	119014	Power Kw:	219
Bodytype:		Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3113
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	Tow bar removable
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		
Adaptive cruise control:			
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

255/45/20/105 Y				
Summer tyres:	Fr.L.	Hankook: 3 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				255/45 R 20 105 Y
Tyre size FR				255/45 R 20 105 Y
Tyre size RL				275/45 R 20 110 Y
Tyre size RR				275/45 R 20 110 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	1		
Total cost ex VAT			1211,12
Bumper spoiler F, Broken, Smart repair			113,74



Bumper F, Stone chip(s), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Door seal FL, Broken, Replace

115,00



Wing trim FL, Damaged, Smart repair

113,74



Alloy rim FL, Scratch(es), Repair and paint (complete)

129,66



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Door RL, Scratch(es), Acceptable

0,00



Charging cable (normal), Missing, Check

0,00



Bumper trim R, Hole, Replace

350,00



Tailgate / Boot, Dent(s) and scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------

