


Vehicle details

VIN	AHTHB3CDX 02134695	Brand	TOYOTA	Maintenance date	-
Licence Plate	VB-R9-0V	Model	Hilux Van 2.4 D-4D-F 4WD Professional Aut Dub Cab	Maintenance mileage	-
Registration date	27/08/2019	Year	2019	Exterior Color	White Solid
Odometer	224 871 km	Engine size	2393	interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	10/04/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Central locking	✓
Electric windows	✓
4x4	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

1



PartDoor


PositionFront left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

2



PartDoor

PositionBack left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

5



PartWing

PositionBack right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

7



PartDoor

PositionBack right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

8



PartDoor

PositionFront right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

9



PartBumper

PositionFront

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

10



PartBonnet

Position-

DamagesDent & Chips

SeverityDiameter (mm) > 20

Repair modeRepair

14



PartTailgate / Boot door

PositionBack

DamagesHail damaged

SeverityDiameter (mm) > 20

Repair modeSmart Repair

15



PartRoof

Position-

DamagesChemical deposit

Severity-

Repair modeFor info

16



PartRear light

PositionBack left

DamagesBroken

Severity-

Repair modeReplace

17



PartRear light

PositionBack right

DamagesScratched

Severity-

Repair modeFor info

Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



●

●

Part	Fabric door lining
Position	Back left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

6



●

●

Part	Fabric door lining
Position	Back right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

12



●

Part	Dashboard
Position	Front
Damages	Perforated
Severity	-
Repair mode	Repair

13



●

●

Part	Cup holder
Position	Front
Damages	Perforated
Severity	-
Repair mode	Replace

Others

11



Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info