



SUBARU Outback 2008 Diesel  
outback 2.0d CM mt

VIN NO JF1BPDLYE8G106940

Registration Number DN792TE



MOT Date

2023-10-12

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2008-07-01

Odometer Reading

165890 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002095255
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive
Seat Colour	Blue	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	153

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Stability control	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Tyre Mobility Kit	

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	PIRELLI PIRELLI-CINTURATO P7	215/55//R17 - 94W / 1 mm
	PIRELLI PIRELLI-CINTURATO P7	215/55//R17 - 94W / 1 mm
	PIRELLI PIRELLI-CINTURATO P7	215/55//R17 - 94W / 2 mm
	PIRELLI PIRELLI-CINTURATO P7	215/55//R17 - 94W / 2 mm

**19 Danni**



## 10 Danni



5/12 - Report Number P20251002095255

13	Fender / Back Left	Bodywork / Poor Previous Repair
14	Panel Filling / Back Right	Interior / Broken
15	Panel Filling / Back Left	Interior / Worn - out
16	Bumper / Back	Bodywork / Dent
17	Tailgate	Bodywork / Poor Previous Repair
18	Spoiler / Back	Paint / Poor Previous Repair
19	Rim / Back Right	Out of Bodywork / Scratch
20	Fender / Back Right	Bodywork / Poor Previous Repair
21	Door / Back Right	Bodywork / Dent
22	Door / Front Right	Paint / Scratch / Line
23	Bumper / Front	Bodywork / Dent
24	Hood	Bodywork / Dent / Small Dent
25	Hood	Bodywork / Poor Previous Repair
26	Windshield / Front	Glass Break / Impact
27	Cant Rail / Left	Bodywork / Poor Previous Repair
28	Cant Rail / Right	Bodywork / Poor Previous Repair
29	Roof Upholstery	Interior / Dirty






1. TV DVD Screen / Front Interior / Non - compliant -



2. Dashboard / Front Interior / Worn - out -



3. Panel Filling / Front Right Interior / Broken -



4. Panel Filling / Front Left Interior / Worn - out -




5. Center Console Interior / Worn - out -



6. Seat / Front Left Interior / Worn - out -





7. Steering Wheel / Front  
Interior / Worn - out -



8. Rim / Front Left  
Out of Bodywork / Scratch -




9. Mirror Shell / Front Left  
Paint / Scratch / Line -



10. Door / Front Left  
Bodywork / Dent -



11. Door / Back Left  
Paint / Scratch / Line -



12. Rim / Back Left  
Out of Bodywork / Scratch -





13. Fender / Back Left  
Bodywork / Poor Previous Repair -



14. Panel Filling / Back Right  
Interior / Broken -



15. Panel Filling / Back Left  
Interior / Worn - out -



16. Bumper / Back  
Bodywork / Dent -



17. Tailgate  
Bodywork / Poor Previous Repair -



18. Spoiler / Back  
Paint / Poor Previous Repair -





19. Rim / Back Right  
Out of Bodywork / Scratch -



20. Fender / Back Right  
Bodywork / Poor Previous Repair -



21. Door / Back Right  
Bodywork / Dent -



22. Door / Front Right  
Paint / Scratch / Line -



23. Bumper / Front  
Bodywork / Dent -



24. Hood  
Bodywork / Dent / Small Dent -






25. Hood  
Bodywork / Poor Previous Repair -



26. Windshield / Front  
Glass Break / Impact -



27. Cant Rail / Left  
Bodywork / Poor Previous Repair -



28. Cant Rail / Right  
Bodywork / Poor Previous Repair -



29. Roof Upholstery  
Interior / Dirty -

## Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

## Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
General			
Test Driven Status	✓		
Equipments Test			
Steering   Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested