



SUBARU XV: 1UQG174

Vinnnumber:	JF1GT7LL5JG047306	Versionname:	2.0Di Premium Lineartronic CVT
First Registrationdate:	6/07/2018	Fiscalpower:	
Expertise Mileage:	137741	Power Kw:	115
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2312
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

225/55/18/92 H				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 92 H
Tyre size FR				225/55 R 18 92 H
Tyre size RL				225/55 R 18 92 H
Tyre size RR				225/55 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3887,46
Seat cover FL, Damaged, Acceptable	0,00



Bumper F, Repaired, Acceptable

0,00



Bonnet, Hail damage, Repair and paint (complete)

511,90



Bumper R, Scratch(es), Replace and paint

686,04



Tailgate / Boot, Dent(s), Repair and paint (complete)

411,74



Alloy rim FR polished, Scratch(es), Acceptable

0,00



Door FR, Dent(s), Replace and paint

1504,60



Wing RR, Bad repair, Check

0,00



Roof, Hail damage, Repair and paint (complete)

773,18

