



SUBARU XV: 1UQG174

Vinnnumber:	JF1GT7LL5JG047306	Versionname:	2.0Di Premium Lineartronic CVT
First Registrationdate:	6/07/2018	Fiscalpower:	
Expertise Mileage:	137741	Power Kw:	115
Bodytype:		Parking lot	2312
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	White
Fueltype:	Petrol		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Steering wheel multifunctional	Luggage cover
Radio multimedia	Sun Roof electric
Seats F heated	Type of Tow bar
Type of GPS	GPS big screen color
Cruise Control	
Type of climate control	Autom climate control
Type of headlighting	Headlighting LED
Number of keys total	2
Type of Lining	Lining artificial leather
	Tow bar fixed

Limited Technical Inspection

Degree of wear

Tyre size RL	225/55 R 18 92 H
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	5.0
Tyre profile depth RR	5.0
Tyre make FR	2480
Tyre size FR	225/55 R 18 92 H
Tyre make RR	2480
Tyre size RR	225/55 R 18 92 H

225/55/18/92 H			
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.
	Re.L.	Vredestein: 5 mm	Re.R.
Tyre profile depth FL	5.0		
Tyre make FL	2480		
Tyre size FL	225/55 R 18 92 H		
Tyre type FR	Summer		
Tyre profile depth RL	5.0		
Tyre make RL	2480		
Tyre type RR	Summer		

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Total cost ex VAT	3887,46
Seat cover FL, Damaged, Acceptable	0,00



Bumper F, Repaired, Acceptable

0,00



Bonnet, Hail damage, Repair and paint (complete)

511,90



Bumper R, Scratch(es), Replace and paint

686,04



Tailgate / Boot, Dent(s), Repair and paint (complete)

411,74



Alloy rim FR polished, Scratch(es), Acceptable

0,00



Door FR, Dent(s), Replace and paint

1504,60



Wing RR, Bad repair, Check

0,00



Roof, Hail damage, Repair and paint (complete)

773,18

