


Vehicle details

VIN	JF1GTELL5 KG096545	Brand	SUBARU	Maintenance date	-
Licence Plate	L8-57-DD	Model	XV 2.0i-S e-BOXER Comfort Lineartronic CVT 5d	Maintenance mileage	-
Registration date	28/04/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	209 122 km	Engine size	1995	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
4x4	✓
Mixed upholstery	✓
Side rails	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Continental 225/55/18 All seasons 5.0 mm		Continental 225/55/18 All seasons 4.5 mm	
Continental 225/55/18 All seasons 4.5 mm		Continental 225/55/18 All seasons 3.5 mm	

Exterior

1



●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



●●

Part	Wing
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

3



●●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



●●

Part	Wing
Position	Front left
Damages	Dented
Severity	-
Repair mode	Repair

5



●●

Part	Bumper
Position	Front
Damages	Misaligned
Severity	-
Repair mode	Adjust

6



●●●●●●

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



●●●

Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

8



●●

Part	Wing
Position	Back left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



●●●

Part	Roof
Position	-
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

10



●●

Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair