

SUBARU Forester Forester 2.0ie Lineartronic



VIN NO JF1SKELL5RG257156 Registration Number L5RG257156

MOT Date

★ 2027-04-01

Last Service

=-

Number of Owners

3 1

Last Service Mileage

2 -

Number of Keys

P2

First Registration Date

2024-04-25

Odometer Reading

⚠ 11123 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250916114834
Inspection Date / Place	2025-09-16 / BCA Berlin	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Hybrid Electric Vehicle Petrol	Road Worthy	Unknown
Colour	Grey	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	154
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			










































Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Remote adjusting wing mirrors
Reversing Camera	Stability control	Electrictailgate	Radio
Tow ball	Alloys wheels	Cruise control	Remote central locking
Roof rails	Electrically folding wing mirrors	LED Headlamps	Rear parking sensors
Equipment Details			
Tow Ball Type	Static	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	17	Seat Heating	Front and Rear
Wheels & Tyres			
Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	7

Cosmetic Damage



1 Tailgate

Paint / Scratch / Scuff



1. Tailgate Paint / Scratch / Scuff -

Mechanical Condition

Control Lights			
Display Defect	•	ABS Warning Light	•
ESP Fault/Traction Control Malfunction Light	⊘	Airbag Warning Light	•
Oil Pressure Warning Light	•	Brake Warning Light	⊘
Power Steering Warning Light	②	Alternator / Battery	•
No Dashboard Lights	•	Tire Pressure Monitoring System	•
Equipments Test			
Main & Spare Keys Functioning	•	Electric Windows	•
Parking Sensors / Cameras Functioning	•	AC / Heating System	•
Other Equipments	•		
Engine			
Engine Status / EML	•	Engine Leak Visible	⊘
Engine Starts	⊘		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide