

Vehicle details

VIN	JM4BP6HH6 01160602	Brand	MAZDA	Maintenance date	-
Licence Plate	J0-36-PZ	Model	Mazda3 SKYACTIV-X 180 5d	Maintenance mileage	-
Registration date	02/10/2020	Year	2020	Exterior Color	Red Metallic
Odometer	47 780 km	Engine size	1998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Yokohama 205/60/16 Summer 4.0 mm		Yokohama 205/60/16 Summer 3.5 mm	
Yokohama 205/60/16 Summer 5.5 mm		Yokohama 205/60/16 Summer 5.0 mm	

Exterior

1



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

2



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

3



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



Part	Step plate
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



Part	Roof wind deflector
Position	Back
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair