DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Vehicle details

VIN	JM4BP6SH6 01210142	Brand	MAZDA	Maintenance date	-
Licence Plate	L2-14-NX	Model	3 E-SKYACTIV-X 186 Comfort 4D	Maintenance mileage	-
Registration date	30/06/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	93 574 km	Engine size	1998	interior Color	Black
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	22/10/2025	Inspection loc.	Dekra Ayvens

Generic equipment

Automated air-conditioning	✔
Cruise control	✔
Leather	✔
GPS system	✔
Alloy wheel rims	✔
Heating seats	✔
Electric seats	✔
Metallic paint	✔
Central locking	✔
Electric windows	✔
Park Distance Control	✔
Audio System	✔
Led lighting	✔

Removable element

Spare wheel kit	✔

Technical Document

User manual	✔
Spare key	✔
Remote key	✔
Sat Nav CD ROM Software	✔

DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Tyres

Bridgestone 215/45/18 Summer 4.0 mm

Bridgestone 215/45/18 Summer 3.5 mm

Bridgestone 215/45/18 Summer 6.5 mm

Bridgestone 215/45/18 Summer 6.5 mm

Exterior

1

Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

2

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

3

Part	Bonnet
Position	-
Damages	Rusty
Severity	-
Repair mode	Lumpsum repair

4

Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

5

Part	Upper door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

6

Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7

Part	Wing
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

8

Part	Door
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

9

Part	Door
Position	Front right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

10

Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

11

Part	Roof
Position	-
Damages	Rusty
Severity	-
Repair mode	Lumpsum repair