

Vehicle details

VIN	JMBXJGK1W JZ002115	Brand	mitsubishi	Maintenance date	-
Licence Plate	SB-49-7H	Model	Eclipse Cross 1.5 DI-T 163pk 2WD First Edition	Maintenance mileage	-
Registration date	09/03/2018	Year	2018	Exterior Color	Grey Metallic
Odometer	184 479 km	Engine size	1499	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	11/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Load cover	✓


Technical Document

User manual	✓
Warranty booklet	✓
Remote key	✓
Spare key	✗

Tyres

Winter kit

Pirelli 225/55/18 Winter 6.0 mm



Pirelli 225/55/18 Winter 6.0 mm



Pirelli 225/55/18 Winter 7.0 mm

Pirelli 225/55/18 Winter 7.0 mm

Exterior

2		Part Position Damages Severity Repair mode	Step plate Front right Dent & Chips - For info
3		Part Position Damages Severity Repair mode	Step plate Back right Dent & Chips - For info
4		Part Position Damages Severity Repair mode	Step plate Back left Dent & Chips - For info
6		Part Position Damages Severity Repair mode	Step plate Front left Dent & Chips - For info
8		Part Position Damages Severity Repair mode	Dash-board and drawer Front Scratched - Repair
10		Part Position Damages Severity Repair mode	Roof - Dent & Chips - Repair
11		Part Position Damages Severity Repair mode	Roof-rail Right Not conform - Replace
12		Part Position Damages Severity Repair mode	Bonnet - Dented - Smart Repair
13		Part Position Damages Severity Repair mode	Bumper Front Dent & Chips - Repair
14		Part Position Damages Severity Repair mode	Wing Front left Chemical deposit - Lumpsum repair
15		Part Position Damages Severity Repair mode	Alloy wheel 18" Front left Scratched - Lumpsum repair
16		Part Position Damages Severity Repair mode	Wing Back left Dented - Smart Repair
17		Part Position Damages Severity Repair mode	Bumper Back Scratched - Repair
18		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips - Repair
19		Part Position Damages Severity Repair mode	Door Front right Dent & Chips - Repair
20		Part Position Damages Severity Repair mode	Alloy wheel 18" Front right Scratched - Lumpsum repair

Interior damage

1		PartSpare key Position- DamagesMissing Severity- Repair modeReplace	5		PartInterior cleaning PositionBack DamagesStained/dirty Severity- Repair modeCleaning
7		PartInterior cleaning PositionFront DamagesStained/dirty Severity- Repair modeCleaning	9		PartBoot carpet PositionBack DamagesScratched Severity- Repair modeRepair