

JMZCR19F600332927

MAZDA 5 5 2.0



TECHNICAL CONDITION

Engine	Brakes	Steering
Engine starts 	Brake operation 	Sounds normal 
Engine operation 	Clutch Clutch operation  Idle sounds normal  Clutch biting point 	Gear Box Automatic shift  Manual shif  Warning light OK 
Engine compartment dry (oil) 		
Fume quantity 		
Sounds normal 		

COMPLAINT NOTE

The technical check includes a visual check of the vehicles without removal of any components.
The condition of the mechanical components cannot be rated.

LEVELS

Coolant fluid	
Brakes fluid	

EQUIPMENT TEST

Electric windows test	
Audio equipment	
Navigation equipment	
AC / Heating system	
Central lock system test	

TYRES

Profile depths

FL 	FR 
BR 	BL 

Additional tyre profil depths

A 3 mm	B 3 mm
C 3 mm	D 3 mm

CONTROL LIGHTS

Dashboard	
ABS	
Oil	
Airbag	
Engine	
Brakes	
Steering	
DPF	
Diesel heaters	
Traction control / ESP / Stability control	
4x4	
Alternator / Battery	



No defects recognizable, good condition or positive tests based on vehicle's age and mileage.



Registered damage that needs to be repaired by the buyer.



Not verifiable.