



# MAZDA CX-3 Diesel

## CX-3 1.8 Exceed navi i-Activsense Technology awd 1

VIN NO JMZDKFW8A00451161  
Registration Number FY277TS



MOT Date

2023-11-16

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2019-12-11

Odometer Reading

99381 km

Country First Registered

Italy

### Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251006115655
Inspection Date / Place	2025-10-06 / BCA Lodi	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	1759
Engine Size	1.8	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	137

### Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			









Equipment


Central locking	Rear parking sensors	Digital Radio	Satellite navigation
Parcel Shef	Remote central locking	Traction control	Tyre Mobility Kit
Power assisted steering	Alloys wheels	Front parking sensors	Volante multifuncion
Remote adjusting wing mirrors	Cruise control	Trip Computer	Stability control

Wheels & Tyres

Mounted Tires

Tyre / Wheel Type	Summer	
	TOYO	215/50//R18 - 92W / 3 mm
	TOYO	215/50//R18 - 92W / 3 mm
	TOYO	215/50//R18 - 92W / 2 mm
	TOYO	215/50//R18 - 92W / 2 mm

### 3 Danni

6/13 - Report Number P20251006115655

13	Rim / Back Left	Out of Bodywork / Scratch
14	Wing Expander / Back Left	Paint / Scratch / Line
15	Fender / Back Left	Bodywork / Dent
16	Tailgate	Bodywork / Dent
17	Bumper / Back	Paint / Scratch / Line
18	Rim / Back Right	Out of Bodywork / Scratch
19	Wing Expander / Back Right	Paint / Scratch / Line
20	Door / Back Right	Paint / Scratch / Line
21	Door / Front Right	Paint / Scratch / Line
22	Roof	Bodywork / Dent / Hail Area
23	Belt / Back Left	Interior / Broken
24	Panel Filling / Front Left	Interior / Scratched
25	Steering Wheel / Front	Interior / Scratched





1. Rim / Front Right  
Out of Bodywork / Scratch -



2. Wing Expander / Front Right  
Bodywork / Dent -



3. Bumper / Front  
Bodywork / Assembly -



4. Bumper / Front  
Bodywork / Dent -



5. Bumper / Front  
Bodywork / Breakage -



6. Grille / Front  
Bodywork / Breakage -





7. Hood  
Paint / Chipping -



8. Windshield / Front  
Glass Break / Impact -




9. Rim / Front Left  
Out of Bodywork / Scratch -



10. Fender / Front Left  
Bodywork / Dent -



11. Door / Front Left  
Paint / Scratch / Line -




12. Door / Back Left  
Paint / Scratch / Line -





13. Rim / Back Left  
Out of Bodywork / Scratch -



14. Wing Expander / Back Left  
Paint / Scratch / Line -



15. Fender / Back Left  
Bodywork / Dent -



16. Tailgate  
Bodywork / Dent -



17. Bumper / Back  
Paint / Scratch / Line -




18. Rim / Back Right  
Out of Bodywork / Scratch -





19. Wing Expander / Back Right  
Paint / Scratch / Line -




20. Door / Back Right  
Paint / Scratch / Line -



21. Door / Front Right  
Paint / Scratch / Line -



22. Roof  
Bodywork / Dent / Hail Area -



23. Belt / Back Left  
Interior / Broken -



24. Panel Filling / Front Left  
Interior / Scratched -





25. Steering Wheel / Front  
Interior / Scratched -

## Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

## Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering   Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested