


Vehicle details

VIN	JMZDM6WHA 00214135	Brand	MAZDA	Maintenance date	-
Licence Plate	L7-35-GS	Model	CX-30 E-SKYACTIV-X 186 Comfort Auto 5d	Maintenance mileage	-
Registration date	20/05/2021	Year	2021	Exterior Color	Red Metallic
Odometer	108 358 km	Engine size	1998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 215/55/18 Summer 7.0 mm



Continental 215/55/18 Summer 7.0 mm



Bridgestone 215/55/18 Summer 5.0 mm



Bridgestone 215/55/18 Summer 5.0 mm

Exterior

1



Part	Step plate
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

3



Part	Unpainted bumper
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

5



Part	Step plate
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	For info

6




Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7



Part	Roof post A/B/C
Position	Left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

Interior damage

2



Part	Other interior
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
hond in voertuig	