

Vehicle details

VIN	JMZDR1WBJ 00105243	Brand	MAZDA	Maintenance date	-
Licence Plate	K3-01-BL	Model	MX-30 E-SKYACTIV 145 First Edition	Maintenance mileage	-
Registration date	27/11/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	63 599 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 215/55/18 Summer 4.5 mm		Bridgestone 215/55/18 Summer 4.0 mm	
Bridgestone 215/55/18 Summer 3.5 mm		Bridgestone 215/55/18 Summer 2.5 mm	

Exterior

1		Part Position Damages Severity Repair mode	Bumper Back Scratched - Repair	2		Part Position Damages Severity Repair mode	Step plate Right Dented - For info
3		Part Position Damages Severity Repair mode	Door Back right Hail damaged Diameter (mm) > 20 Smart Repair	4		Part Position Damages Severity Repair mode	Alloy wheel 18" Back right Scratched - Lumpsum repair
5		Part Position Damages Severity Repair mode	Door Front right Dented Number > 2 Smart Repair	6		Part Position Damages Severity Repair mode	Bonnet - Dented Diameter (mm) > 20 Smart Repair
7		Part Position Damages Severity Repair mode	Bumper Front Scratched - Repair	8		Part Position Damages Severity Repair mode	Alloy wheel 18" Front left Scratched - Lumpsum repair
9		Part Position Damages Severity Repair mode	Door Front left Dented Number > 2 Smart Repair	10		Part Position Damages Severity Repair mode	Door Back left Dented Diameter (mm) > 20 Smart Repair
11		Part Position Damages Severity Repair mode	Wing Back left Dent & Chips - Repair	12		Part Position Damages Severity Repair mode	Wing moulding Back left Scratched - Repair
14		Part Position Damages Severity Repair mode	Step plate Left Dent & Chips - For info				

Interior damage

13



Part	Fabric seat
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

15



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair