

Vehicle details

VIN	JMZDR1WBJ 00119450	Brand	MAZDA	Maintenance date	-
Licence Plate	N2-73-BK	Model	MX-30 E-SKYACTIV 145 Comfort auto	Maintenance mileage	-
Registration date	10/09/2021	Year	2021	Exterior Color	Black Metallic
Odometer	52 729 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	12/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 215/55/18 Summer 3.0 mm		Bridgestone 215/55/18 Summer 3.0 mm	
Bridgestone 215/55/18 Summer 4.5 mm		Bridgestone 215/55/18 Summer 4.5 mm	

Exterior

1



Part

Step plate

Position

Front right

Damages

Dent & Chips

Severity

-

Repair mode

For info

2



Part

Roof

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

4



Part

Bonnet

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

5



Part

Wing

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Repair

6



Part

Door

Position

Front left

Damages

Scratched


Severity

-

Repair mode

Repair

7



Part

Door

Position

Back left

Damages

Scratched


Severity

-

Repair mode

Repair

8



Part

Door

Position

Front right

Damages

Dent & Chips

Severity

-

Repair mode

Repair

9



Part

Alloy wheel 18"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

Interior damage

2



Part	Steering wheel
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info