



MAZDA 6

6 2.2 Kombi SKYACTIV-D Aut.

VIN NO JMZGJ691821112396
Registration Number 1821112396



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	3	2	265954 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-07-24	-

Inspection Report Summary


Customer	BCA Online	Report Number	P20250904113433
Inspection Date / Place	2025-09-04 / ARS Altmann AG Wolnzach	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	2191
Engine Size	2.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	129
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Diesel particulate filter
Remote adjusting wing mirrors	Roof rails	Stability control	Central locking
Leather steering wheel	Rear parking sensors	Tow ball	Alloys wheels
Cruise control	Front parking sensors	Remote central locking	Satellite navigation
CD Player	Electrically folding wing mirrors	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

20 Schäden



21 Schäden



Component		Damage	Comments
1	Side Panel / Back Right	Paint / Poor Previous Repair	
2	Door / Back Right	Paint / Poor Previous Repair	
3	Door / Front Right	Paint / Poor Previous Repair	
4	Door / Front Right	Paint / Poor Previous Repair	
5	Hood	Bodywork / Dent / Dent	
6	Side Panel / Back Left	Bodywork / Dent / Dent	
7	Side Panel / Back Right	Bodywork / Dent / Dent	
8	Bumper / Front	Paint / Stone Chip	
9	Wing Repeater / Left	Bodywork / Dent / Dent	
10	Door / Front Left	Paint / Scratch / Scuff	
11	Seat / Front Left	Interior / Dirty	
12	Door / Back Left	Paint / Scratch / Scuff	

13	Seat / Back Center	Interior / Dirty
14	Rim / Back Left	Out of Bodywork / Scratch
15	Side Panel / Back Left	Paint / Scratch / Scuff
16	Bumper / Back	Paint / Scratch / Scuff
17	Bumper / Back	Paint / Scratch / Scuff
18	Rim / Back Right	Out of Bodywork / Scratch
19	Door / Back Right	Paint / Scratch / Scuff
20	Door / Front Right	Paint / Scratch / Scuff
21	Mirror Shell / Front Right	Paint / Scratch / Scuff
22	Bumper / Front	Paint / Scratch / Scuff



1. Side Panel / Back Right
Paint / Poor Previous Repair -



2. Door / Back Right
Paint / Poor Previous Repair -




3. Door / Front Right
Paint / Poor Previous Repair -



4. Door / Front Right
Paint / Poor Previous Repair -



5. Hood
Bodywork / Dent / Dent -



6. Side Panel / Back Left
Bodywork / Dent / Dent -



7. Side Panel / Back Right
Bodywork / Dent / Dent -



8. Bumper / Front
Paint / Stone Chip -



9. Wing Repeater / Left
Bodywork / Dent / Dent -



10. Door / Front Left
Paint / Scratch / Scuff -




11. Seat / Front Left
Interior / Dirty -



12. Door / Back Left
Paint / Scratch / Scuff -



13. Seat / Back Center
Interior / Dirty -



14. Rim / Back Left
Out of Bodywork / Scratch -



15. Side Panel / Back Left
Paint / Scratch / Scuff -




16. Bumper / Back
Paint / Scratch / Scuff -




17. Bumper / Back
Paint / Scratch / Scuff -



18. Rim / Back Right
Out of Bodywork / Scratch -



19. Door / Back Right
Paint / Scratch / Scuff -



20. Door / Front Right
Paint / Scratch / Scuff -



21. Mirror Shell / Front Right
Paint / Scratch / Scuff -



22. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Diesel Particulate Filter Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Starts	✓
---------------------	---	---------------	---

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA
--------------	----

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)